

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1940, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-07674

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

SOUTH HOBBS GB/SA UNIT

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

ALTURA ENERGY, LTD.

8. Well No.

94

3. Address of Operator

PO BOX 4294 HOUSTON TX 7710-4294

9. Pool name or Wildcat

HOBBS GRAYBURG/SAN ANDRES

4. Well Location

Unit Letter N : 330 Feet From The SOUTH Line and 2310 Feet From The WEST Line

Section 10 Township 19-SOUTH Range 38-EAST NMPM LEA N.M. County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3588.5' G.L.

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) RIHW/2-3/8" W.S. TAG CIBP @ 3050' +/-
- 2) CIRC WELL W/9.5# 32VIS MLB.
- 3) CAP CIBP W/35sx CLASS (C) NEAT CMT 3950'-3814'
- 4) PERF 4 HOLES @ 2800', SET 8-5/8". REF @ 2700' SQZ 50 SX UNDER CAP w/35 SX CMT (C) NEAT
- 5) PERF 4 HOLES @ 1735, SET 8-5/8 REF @ 1635' SQZ 50 SX UNDER CAP W/35 SX CMT
- 6) PUH TO 168' SPRT 35 sx CLASS (C) NEAT 168'-32'
- 7) PUH TO 30' FILL WELL W/CMT
- 8) CUT OFF HEAD INSTALL DRY HOLE MARKER

..NOTIFY OCD 24 HRS PRIOR TO RIGGING UP..

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Roger Massey

P&A SUPERVISOR

TITLE

DATE 11-17-97

TYPE OR PRINT NAME

ROGER MASSEY

TELEPHONE NO. 915-530-0907

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY

TITLE

DATE

NOV 17 1997

CONDITIONS OF APPROVAL, IF ANY: