

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☐

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER - Injection	7. Unit Agreement Name
Name of Operator Amoco Production Company			8. Farm or Lease Name South Hobbs Unit
Address of Operator P. O. Box 68 Hobbs, NM 88240			9. Well No. 76
Location of Well UNIT LETTER E 1980 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 10 TOWNSHIP 19-S RANGE 38-E NMPM.			10. Field and Pool, or Wildcat Hobbs Grayburg San Andres
15. Elevation (Show whether DF, RT, GR, etc.)			12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to increase injection by the following method:

Pull tubing and packer. Run CIBP and set 3400'. Perf 3170' w/4 JSPF.
Run tubing and packer. Set packer at 3100'. Cement casing with 1600 SX of
Class "C" Cmt. Run bit and drill out retainer and cement. Test perfs to
500 psi. Acidize w/5000 gallons in 3 stages. Return well to injection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Mitchell TITLE Assist. Admin. Analyst DATE 12-9-80

Orig. Signed by

Jerry Sexton

Dist. 1, Sup.

APPROVED BY _____ TITLE _____ DATE DEC 12 1980

CONDITIONS OF APPROVAL, IF ANY: 0+4-NMOCD, H 1-Susp 1-GPM 1-Hou

