STATE CE NEW MEXICO ENERGY AND MINERALS DEPARTMENT

ne er corité ecccives	
DISTRIBUTION	
BANTA FE	
FILE	
U.\$ G.\$,	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

Farm C-103 -

			'VICO OTCAL		Resise	
SANTA PE FILE	S,	ANTA FE, NEW ME	.XICO 87501			
U.S.G.S.				ì	dicate Type of Lesse	رعار
LAND OFFICE				L		F., 0
OPERATOR				5. Stat	te Oil & Gas Lease N	o.
						m
ICO HOT LIL THIS FORM	SUNDRY NOTICES AN			m. ()		
USE "A	PPLICATION FOR PERMIT -"	(FORM C-101) FOR SULL PRO	POSALS.)	7, Uni	t Agreement Nose	777777
OIL X WELL	OTHER-					
Name of Operator				8. For	m or Lease Name	
Amoco Production	Company			Sou	uth Hobbs (GS	A) Unii
Address of Cylerator				9. 801	l No.	
P. O. Box 68, H	obbs, NM 88240				. 77	
Location of Well					eld and Pool, or end	
UNIT . CTTEP	. 1980 FEET FA	ion the North Li	NE AND1980	FEET FROM HODE	os Grayburg S	an Andı
Mos+	10	10.0	20 5			
THE WEST TIME	., SECTION	_ TOWNSHIP	_ RANGE	MAPM.		
THIII HATTI	1111111 15. Ele	vation (Show whether DF, h	RT, GR, etc.)	12. 00	ounty (1)	1444
	(1)				_ea \\\\\	
C	heck Appropriate Bo	ox To Indicate Natur	e of Notice Repo	ort or Other Da	***	777777
	OF INTENTION TO:	I lo marcate statur		SEQUENT REPO		
					J	
RFORM BEMEDIAL WORK	PL	UG AND ABANDON REM	EDIAL WORK		ALTERING CASING	
MPORARILY ABANSON		сом	MENCE DRILLING OPNS.		PLUG AND ABANDO	MENT
		i				
LL OR ALTER CASING	СН	ANGE PLANS CASI	ING TEST AND CEMENT JO	ه		
LL OR ALTER CASING	сн		ING TEST AND CEMENT JQ	· []		
OTHER Describe Progrased or Comp. worky SEE RULE 1103.			ТНЕЯ		ed date of starting on	proposed
OTHER	se production by ump. Set a packe Pump 4000 gal.	the following me er at 3950'. Run of Versagel and	other. thod: GR and temper:	. including estimate ature base 1	og	y proposed
Propose to increase Propose to increase Propose to increase Propose to increase Pull tubing and put from 3900'-4145'. Flush with 26 bbls	se production by ump. Set a packe Pump 4000 gal. s. of water. Ins	the following me er at 3950'. Run of Versagel and stall pumping equ	thod: GR and tempera 4000 gal. of A	. including estimate ature base 1	og ction.	proposed
Propose to increase Propose to increase Pull tubing and put from 3900'-4145'. Flush with 26 bbls Plush with	se production by ump. Set a packe Pump 4000 gal. s. of water. Ins	the following me er at 3950'. Run of Versagel and stall pumping equ	nd give pertinent dates. thod: GR and tempera 4000 gal. of A: ipment and return	ature base 1 SOL mixture. urn to produ	og ction.	