

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-07687 07698

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

South Hobbs (GSA) Unit

1. Type of Well

OIL
WELL ☐

GAS
WELL ☐

OTHER

Water Injector

2. Name of Operator

Amoco Production Company

(Room 18.108)

8. Well No.

110

3. Address of operator

P.O. Box 3092, Houston, Texas 77253-3092

9. Pool name or Wildcat

Hobbs Grayburg San Andres

4. Well Location

Unit Letter I : 2310 Feet From The South Line and 990 Feet From The East Line

Section 15 Township 19-S Range 38-E NMPM Lea, NM County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3604' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

- 1) MIRUSU (Notify NMOCDD within 24 hrs before job)
- 2) POH x Inj. Eqpt.
- 3) RIH x CIBP x SA 4025'. Cap x 50' cmt (check x NMOCDD)
Load hole x 9.5# mud brine.
- 4) Spot 100' cmt pug 2650'-2550'. B7QY
- 5) Perf 50' below shoe x 451' x pmp 100' cmt inside/outside casing
- 6) Cap x 10 sxs cmt at surface.
- 7) Install PxA marker/cut off wellhead.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry M. Sexton TITLE Staff Assistant DATE 03-15-94

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAR 22 1994

PxA 3 94

SOUTH HOBBS UNIT WELL 110

July 27, 1993
FLAC # 95280101

PROPOSED

0 - 10' CEMENT PLUG

401 - 501' CEMENT PLUG
Formerly Frank Seima Well #1
0 - 451' SURF CSG w/200 sx cmt

2550 - 2650' CEMENT PLUG

4025 - 4025' CIBP
3975 - 4025' CEMENT
0 - 4178' PROD CSG w/550 sx cmt

KB ELEV: 3604'
TD: 4238'

3230 - 4182' CORE

4086 - 4095' PERFS w/2 JSPF
4124 - 4143' PERFS w/2 JSPF
4178 - 4238' HOLE
4149 - 4164' PERFS w/2 JSPF

SMITH HOBBS UNIT WELL 110

July 27, 1993

FLAC # 95280101

CURRENT

0 - 451' SURF CSG w/200 sx cmt

Formerly: Frank Selman No. 2

0 - 4178' PROD CSG w/550 sx cmt

KB ELEV: 3604'

TD: 4238'

3230 - 4182' CORE

4086 - 4095' PERFS w/2 JSPF

4124 - 4143' PERFS w/2 JSPF

4178 - 4238' HOLE

4149 - 4164' PERFS w/2 JSPF