submit 3 Copies to Appropriate District Office State of New Mexico
Energy, 1 rals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I

## OIL CONSERVATION DIVISION

ELL API NO.		
	20 025-0769-8	

P.O. Box 1980, Hobbs, NM 88240 P.O.Box 20	30-025-0769-4		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico	5. Indicate Type of Lease  STATE FEE X		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.		
SUNDRY NOTICES AND REPORTS ON (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEE	WELLS PEN OR PLUG BACK TO A		
DIFFERENT RESERVOIR. USE "APPLICATION FOI (FORM C-101) FOR SUCH PROPOSALS.	PERMIT"		
1. Type of Well OIL GAS WELL OTHER			
2. Name of Operator	8. Well No.		
Amoco Production Company (Room 18.108 W			
3. Address of operator	9. Pool name or Wildcat		
P.O. Box 3092, Houston, Texas 77253-	Hobbs Grayburg San Andres		
4. Well Location Unit Letter J :2310 Feet From The Sou	th Line and 2310 Feet From The East Line		
Section 15 Township 19-S	Range 38-E NMPM Lea, NM County		
	tether DF, RKB, RT, GR, etc.) 3594' DF		
11. Check Appropriate Box to Indicat	e Nature of Notice, Report, or Other Data		
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING		
MPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT			
PULL OR ALTER CASING	CASING TEST AND CEMENT JOB		
OTHER:	OTHER:		
12. Describe Proposed or Completed Operations (Clearly state all pertinent work.) SEE RULE 1103.	letails, and give pertinent dates, including estimated date of starting any proposed		
POH X RIH X CIBP X SA 3950' (APPROVE	LD RODS X RTXIB X PTG X PIH X BIT X SCRAPER X D BY PAUL KAUTZ W/NMOCD) X LOAD X TEST X 750 CAP CIBP X 25 SX CMT FROM 3702' TO 3950' X SPOT		

DIG OUT CELLAR X MIRUSU (6/27/94) X LD RODS X RTXIB X PTG X PIH X BIT X SCRAPER X POH X RIH X CIBP X SA 3950' (APPROVED BY PAUL KAUTZ W/NMOCD) X LOAD X TEST X 750 PSI X OK. DISPLACE CSG X 10# MUD X CAP CIBP X 25 SX CMT FROM 3702' TO 3950' X SPOT CMT PLUG FROM 2752' TO 3050' X 30 SX CMT X SPOT CMT PLUG FROM 1450' TO 1748' X 30 SX CMT. RIG UP WL TRUCK X PERF 208'-210' X 4 SPF X UNABLE TO CIRC TO SURFACE BETWEEN CSG STRINGS 13-3/8" X 8-5/8" X 7" X 5-1/2" X UNABLE TO PMP DN CSG STRINGS X FLUID GOING DOWN X PMP 5 BBLS ZONE LOK X 42 SX CMT X 5 BBLS CACL2 WATER X 42 SX CMT X 5 BBLS CACL2 WATER X 30 SX CMT X WOC X 2 HR X TAG CMT 134' FROM SURF X PMP 30 SX CMT X WOC X 1 HR X PMP 70 SX CMT X CIRC CMT TO SURF IN 5-1/2" CSG X WOC. CHECK CMT X CMT AT SURFACE X CUT OFF WELL HEAD X INSTALL PXA MARKER X CUT OFF DEAD MEN X FILL IN CELLAR X CLEAN LOCATION X RDMOSU (7/1/94)

Engineer: Terry Caldwell (713)366-7286

I hereby certify that the information above is true and complete		
SIGNATURE LEXIMONI Fleener	TITLE Staff Assistant	DATE 07-07-94
TYPE OR PRINT NAME	Devina M. Prince	TELEPHONE NO. (713) 366-7686
(This space for State Use)  APPROVED BY  CONDITIONS OF APPROVAL, IF ANY	cr. a cas merector	AUG 24 190

