

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-09891</u>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name COOPER 'A'
2. Name of Operator Shell Western E&P Inc.	8. Well No. 1
3. Address of Operator P.O. Box 576 Houston, TX 77001-0576 (WCK 4587)	9. Pool name or Wildcat EUNICE MONUMENT (G/SA)
4. Well Location Unit Letter <u>B</u> : <u>330</u> Feet From The <u>NORTH</u> Line and <u>2310</u> Feet From The <u>EAST</u> Line Section <u>4</u> Township <u>20S</u> Range <u>37E</u> NMPM LEA County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3563' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: DO CICR'S; PREP FOR UNITIZATION ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-05 TO 2-13-92:

RIH W/WS. PT CSG TO 500# FOR 30 MIN, HELD. DO CICR @ 1147' & UNDERLYING CMT TO 1265',
FELL FREE. PT CSG TO 500# FOR 15 MIN, HELD. TAG TOC @ 2368'. DO 4' CMT & BEGAN
DRLG ON CICR. DO CICR & UNDERLYING CMT TO 2420', FELL FREE. TAG CMT AGAIN @ 2485' &
DRLD TO 2527', FELL FREE. PT CSG TO 500#, HELD. RETD WELL TO TA'D STATUS.
(WORK WITNESSED BY AMERADA HESS PROD FOREMAN.)

WELL IS NOW READY TO BE ACCEPTED INTO AMERADA'S NORTH MONUMENT GRAYBURG/SAN ANDRES UNIT.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE W. F. N. Kelldorf TITLE TECH. MANAGER - ENVIR. ENG. DATE 3/23/92
TYPE OR PRINT NAME W. F. N. KELLDORF TELEPHONE NO. 713/870-3426

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

MAR 26 1992

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: