

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B1626	
7. Unit Agreement Name	
8. Farm or Lease Name State "V"	
9. Well No. 3	
10. Field and Pool or Wildcat EUMONT QUEEN (Gas) EUNICE-MONUMENT (G-SA)	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Dual - Oil & Gas	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator Drawer "D", Monument, New Mexico 88265	
4. Location of Well UNIT LETTER H 2310 FEET FROM THE North LINE AND 330 FEET FROM East THE LINE, SECTION 36 TOWNSHIP 19-S RANGE 36-E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 3600' DF	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
-------------------------	-----------------------

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER Blank off & Abandon G-SA Zone <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pulled straight thru tool from PSI Nipple. Ran lockdown blanking plug and set in PSI nipple at 3775'.

Grayburg-San Andres Zone Blanked off and abandoned.

Producing Eumont Queen gas zone.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M. O. Black TITLE Supver., Admin. Services DATE 8-25-72

APPROVED BY Joe D. Ramey TITLE Dist. I, Supv. DATE AUG 30 1972

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 20 1972

OIL CONSERVATION COMM.
HOBBS, N. M.