

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO.	30-025-12482
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	A01543 Assignment 1
7. Lease Name or Unit Agreement Name	
Graham State NCT "F"	
8. Well No.	7
9. Pool name or Wildcat	Monument ABO

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> Convert to SWD	2. Name of Operator Chevron USA
3. Address of Operator P.O. Box 67 Monument NM 88265	4. Well Location Unit Letter <u>O</u> : <u>1650</u> Feet From The <u>East</u> Line and <u>330</u> Feet From The <u>South</u> Line Section <u>36</u> Township <u>19S</u> Range <u>36E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3577'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: Plug ABO open lower San Andres for SWD ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 6850'
2. TST Csg 300# f/30 min.
3. Circ. Cmt f/6850' to 4900'
4. Tag TOC
5. Perf Lower San Andres 4800' - 4554'
6. Acidize 8000 gal NEFE HCL DI 15% Acid w/Rock Salt Block
7. Set Inj Pkr on 2 3/8" Tbg at \pm 4500'
8. Load and tst bksd
9. Put on Inj

Approximate start date 20 October 1994

NOTE: SWD ADMINISTRATIVE ORDER NO. SWD-561

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Forrest C. Noah TITLE Plant Mgr. DATE 10-17-94
TYPE OR PRINT NAME FORREST C. NOAH TELEPHONE NO. (505)-393-2823

(This space for State Use)

Only Signed by
Paul Kutz
Geologist

OCT 18 1994

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

OCT 17 1994

OFFICE