

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Aramis, NM 88210

DISTRICT III
1000 Rio Arizos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-12544

1. Indicate Type of Lease
STATE ☒ FEDERAL ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
CHEVRON U.S.A. INC.

3. Address of Operator
P.O. Box 1150 Midland TX 79707 Rm #37

4. Well Location
Unit Letter B : 660 Feet From The North Line and 1980 Feet From The East Line

Section 36 Township 20S Range 36E NMPM LEA County LEA

10. Elevation (Show whether OF, RKB, RT, GR, etc.)
3554

7. Lease Name or Unit Agreement Name
EUNICE MONUMENT South Unit

8. Well No.
139

9. Pool name or Wildcat
EUNICE MONUMENT GB/SA

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: Sq2 perf Polymer Sq2 Re perf + ACD'z ☒

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

RIH W/CICR + SET @ 3700' sq2 All perfs from 3764' to 3992'.
D/O CICR + CMT to 3800' spot 250g 15% NEFE acid @ 3795 set pkr @
3690 ±. Break down perfs 3764-69 + 3780-90. RIH W/CICR + SET @ ± 3700
Do polymer sq2 + Batch mix cmt sq2 (75 to 150 sx) sq2,
RIH D/O cmt. CICR to ORIGINAL PBTD 4002. RIH W/4" cs9 guns + perf
from 3804-3992 1JHPF total of 89 holes. ACD'z perfs 3940'-92' (18 holes) set
pkr @ 3920. ACD'z W/1350g 15% NEFE HCL. Set pkr @ 3795 ACD'z perfs 3804-
3902 W/3000g 15% NEFEHCL Swab back. Run rods + tbg. Return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE E.O. Doherty TITLE Drilg. TA.

TYPE OR PRINT NAME E.O. DOHERTY DATE 9/25/90

TELEPHONE NO. 915 681-2812

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: