

NEW MEXICO STATE LAND OFFICE
SANTA FE, NEW MEXICO

DEPARTMENT OF THE STATE GEOLOGIST
SANTA FE

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

Mr. C. G. Staley Hobbs, N. Mex., 1-11 1930
Santa Fe, New Mexico.

Dear Sir:

You are hereby notified that it is our intention to abandon O. B. Terry Well
No. 1 in W $\frac{1}{2}$ NE $\frac{1}{4}$ of Sec. ---- of Sec. 22, T. 19s, R. 38E,
N. M. P. M., Hobbs Oil Field, Lea County.
We plan to commence work on 12-5, 1929.

The reasons for wishing to abandon the well are as follows:

DRY HOLE

The present condition of the well is as follows:

Hole full bottom hole salt water.

The work which we propose to do in abandoning the well is as follows:

**Plug off bottom water with steel cuttings and lead wool, bail dry,
dump 25 sacks cement on lead plug, fill with mud and salvage casing,
filling hole with mud after pulling each string.**

Approved Jan 14 30 1930

Except as follows:

A. L. Staley
State Geologist or Oil and Gas Inspector.

Sincerely yours,
SHELL PETROLEUM CORP.

By [Signature] Company or Operator.

Position _____

Send communications regarding this well to

Name _____

Address _____