DISTRIBUTION	
SANTAL	NEW ME O OIL CONSERVATION COMMES N Form C-101
F)_E	The state of the s
L. S. G. S.	Santa Fe, New Mexico
LANE OFFICE	
TRANSPORTER GAS	
PHORATION OFFICE	NOTICE OF INTENTION TO DRILL to the District Office of the Oil Conservation (Complission and approved plan are considered additional additional and approved plan are considered additional additiona
tions of the Commission.	NTUPLICATE. One copy will be returned following approval. See additional instructions in Rules and Regula If State Land submit 6 Copies Attach Form C- 128 in triplicate to first 3 copies of form C-10
	bbsNew Mexico
	The state Land submit a Copies Attach Form G- 128 in triplicate to first 3 copies of form G-10
OIL CONSERVATION C	bbs. New Mexico 10-23-63 (Date) COMMISSION
	bbs. New Mexico 10-23-63 (Date) COMMISSION

(GIVE LOCATION FROM SECTION LINE)

В

G

J

O

*Cement is to circulate

SLO

**Cement is to return to 2,400'.

OIL CONSERVATION COMMISSION

ABS

FILE

A

H

ĩ

p

Size of Casing

We propose to use the following strings of Casing and to cement them as indicated:

If changes in the above plans become advisable we will notify von immediately.

ADDITIONAL INFORMATION (If recompletion give full details of proposed plan of work.)

D

E

f.

M

11"

X

 \mathbf{C}

F

K

N

Size of Hole

6 3/4

Approved

(6)

Except as follows:

NMOCC

State A-17 (Lease) Veil No. 7 in M (Unit) The well is

CASING PROGRAM

New

Weight per Foot

Monument

Sacks Cement

200#

350**

line and 330 feet from the

19S R 37E NMPM.

Part Lea If State Land the Oil and Gas Lease is No... 13988

Drilling Contractor Roy H. Smith Drilling Company

Wichita Falls, Texas

formation at an approximate depth of 4,000 feet.

Depth

350

<u> 3990</u>

Position Asst. Dist. Superintendent

Name.....Continental 011 Company Address Box 460, Hobbs, N. M.

Send Communications regarding well to

We propose to drill well with drilling equipment as follows: Rotary Tools

We intend to complete this well in the Grayburg-San Andres

New or Second Hand

Sincerely yours,

The status of plugging bond is Blanket