STATE OF NEW ME		: 	
ENERGY AND MINERALS	<del></del>		Form C-103
NO. OF COPIES RECEI	/ED OIL CONSE	RVATION DIVISION	Revised 10-1-7
DISTRIBUTION		• Box 2088	
SANTA FE	SANTA FE,	NEW MEXICO 87501	5a. Indicate Type of Lease
FILE			State Fee X
U.S.G.S	<del></del>		
LAND OFFICE	<del></del>		5. State OII & Gas Lease No.
OPERATOR			į
<del></del>	SUNDRY NOTICES AND REPORTS ON	WELL C	_
(DO NOT USE THIS FO		··	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
RESERVOIR	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT-" (FORM C-1011 FOR SUCH PROPOSALS.)		
. 01L	GAS	OCH C-TOTT FOR SUCH PROPUSALS.)	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
WELL X	WELL OTHER		7. Unit Agreement Name
. Name of Operator			8. Farm or Lease Name
Read & Stevens, Inc.			Snyder
. Address of Operator			9. Well No.
P.O. Box 1518, Roswell, NM 88201			1
. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER J . 2310 FEET FROM THE East LINE AND 2310 FEET FROM			West Teas Yates
	. SECTION 16 TOWNSHIP	20S RANGE 33E NMPM	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX			12. County XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
×××××××××××××××××××××××××××××××××××××××			Lea XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
NOTIC	Check Appropriate Box To Indica E OF INTENTION TO:	ate Nature of Notice, Report or Oth SUBSEQUENT RE	er Data
PERFORM REMEDIAL I		REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDO	<u>├</u>	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT X
PULL OR ALTER CASI	√c	CASING TEST AND CEMENT JOB	
OTHER		OTHER	
·			
escribe Proposed or	Completed Operations(Clearly sta	te all pertinent details, and give	pertinent dates, including esti-
ated date of startin	g any proposed work) SEE RULE 11	03.	,
9-1-83	Sat CIPR 30501 P +		
J 1.05	Set CIPB 3050'. Prep to spot cm	Ť•	
9-2-83	Pumped 105BBLS mud @ 3050', pump 25sx cmt on vacuum, SD 4hrs @ 3050', pump 15sx cmt pressured up,		
	broke circ, pull tubing, spot 35sx @ 2700'.		
9-6-83	Tag @ 2410', 35sx plug set @ 1456'-1356', 10sx surface plug w/Dryhole marker.		
	Cleaning up location. Will Noti	fy when ready for inspection.	
hereby certify tha	the information above is true	and complete to the best of my know	aladae and hall if
	777.00 00010 13 1100	And combine to the Dest Of MA KNOT	rieuge and beliet.

TITLE Drilling & Production Manager

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

DATE 9-8-83

DATAPR ?

1984

RECEIVED

**SEP** 9 1983

O.C.D.