

5-18-64 - cont -
2 hr FSIP 4477#.

5-25-64 TD 10985', PBD 10864', prep to squeeze.
Perf 10731-736' W/4 SPF
Ac. 1000 gals.
Swbd 44 BLO, 24 BAW & 36 BFW/5 hrs.

6-1-64 TD 10985', PBD 10510', prep to P&A.
Squeezed perfs 10731-736' W/50 sx.
DO 10510'
Perf 9676-81' W/4 SPF
Swbd 25 BO + 60 BW/11 hrs, natural.
Ac. 500 gals. 9676-81'.
Swbd 15 BNO + 147 BFW. In 21 hrs.
Perf 10369-403' W/10 shots
Ac. 1250 gals. 10369-403'.
Swbd 5 BAW & swbd dry in 3 hrs.

6-8-64 TD 10985', PBD 10510', prep to P&A.
Perf 9702-05' W/5 shots
Perf 9721-25' W/5 shots.
Ac. 750gals 9702-25'.
Swbd 1 BO + 55 BW/3 hrs.

6-15-64 TD 10985', PBD 10510', prep to P&A.

6-22-64 TD 10985', PBD 10510', prep to P&A.

6-29-64 TD 10985', PBD 10510', prep to P&A.

7-6-64 TD 10985', PBD 10510', prep to P&A.

7-13-64 TD 10985', PBD 10510', prep to P&A.

7-20-64 TD 10985', PBD 10510', prep to P&A.

9-8-64 TD 10985', PBD 9715', PLUGGED & ABANDONED.
Set BP @ 9715'
Pmpd 496 BO + 91% wtr in 20 days from perfs
9676-9705'.