DISTRIBUTION SANTA FE		
SANTA FE		Supersedes Old C-102 and C-103
	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State X
OPERATOR		5. State Oil & Gas Lease No.
		E-4207
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
·•	The state of the state proposals.)	7. Unit Agreement Name
WELL WELL	OTHER-	
2. Name of Operator		8. Farm or Lease Name
Shoreline Expl	oration Co	
. Address of Operator	7-5	Snyder 9. Well No.
Box 1822, Ross	well N M	_
. Location of Well	WELL, IV. IVI.	10. Field and Pool, or Wildcat
UNIT LETTER,	1090 FEET FROM THE South LINE AND 2310 FEET	West Teas
THE East LINE, SE	ECTION 16 TOWNSHIP 20S RANGE 33E	MPM. (
	15 Floretten (Standard DE DE DE CE	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3542' GL	Lea
Chec	ck Appropriate Box To Indicate Nature of Notice, Report or	Other Data
NOTICE OF		IENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
EMPORARILY ABANDON	COMMENCE DRILLING OPNS.	<u> </u>
ULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
		· · · · · · · · · · · · · · · · · · ·
OTHER	OTHER	
7. Describe Proposed or Complete	d Operations (Clearly state all pertinent details, and give pertinent dates, incli	ding estimated data of estation and a
work! SEE BUILT 1605		wing estimated date of Starting any proposed
work) SEE RULE 1 103.		using estimated date of starting any proposed
work) SEE RULE 1 fos.		using estimation date of starting any proposed
work) SEE RULE 1103.		aving estimateed dute of starting any proposed
	andoned May 17, 1965. Cement plugs set as fo	
	sandoned May 17, 1965. Cement plugs set as fo 10 sx at surface	
	sandoned May 17, 1965. Cement plugs set as fo 10 sx at surface 25 sx 315' - 415'	
	sandoned May 17, 1965. Cement plugs set as fo 10 sx at surface	
	sandoned May 17, 1965. Cement plugs set as fo 10 sx at surface 25 sx 315' - 415'	
	pandoned May 17, 1965. Cement plugs set as fo 10 sx at surface 25 sx 315' - 415' 25 sx 1420' - 1520' 25 sx 2800'- 2900'	
P lugged and a b	osndoned May 17, 1965. Cement plugs set as fo 10 sx at surface 25 sx 315' - 415' 25 sx 1420' - 1520' 25 sx 2800'- 2900' 25 sx 3195' - 3295'	llows:
Plugged and ab	pandoned May 17, 1965. Cement plugs set as for 10 sx at surface 25 sx 315' - 415' 25 sx 1420' - 1520' 25 sx 2800' - 2900' 25 sx 3195' - 3295' atted between plugs. Installed customary $4\frac{1}{2}$ ' x	llows:
P lugged and a b	pandoned May 17, 1965. Cement plugs set as for 10 sx at surface 25 sx 315' - 415' 25 sx 1420' - 1520' 25 sx 2800' - 2900' 25 sx 3195' - 3295' atted between plugs. Installed customary $4\frac{1}{2}$ ' x	llows:
Plugged and ab	pandoned May 17, 1965. Cement plugs set as for 10 sx at surface 25 sx 315' - 415' 25 sx 1420' - 1520' 25 sx 2800' - 2900' 25 sx 3195' - 3295' atted between plugs. Installed customary $4\frac{1}{2}$ ' x	llows:
Plugged and ab	bandoned May 17, 1965. Cement plugs set as for 10 sx at surface 25 sx 315' - 415' 25 sx 1420' - 1520' 25 sx 2800' - 2900' 25 sx 3195' - 3295' atted between plugs. Installed customary $4\frac{1}{2}$ ' xillows:	llows:
Plugged and ab	pandoned May 17, 1965. Cement plugs set as for 10 sx at surface 25 sx 315' - 415' 25 sx 1420' - 1520' 25 sx 2800' - 2900' 25 sx 3195' - 3295' attend between plugs. Installed customary $4\frac{1}{2}$ ' xillows: Shoreline Exploration Co. #2 Snyder	llows:
Plugged and ab	bandoned May 17, 1965. Cement plugs set as for 10 sx at surface 25 sx 315' - 415' 25 sx 1420' - 1520' 25 sx 2800' - 2900' 25 sx 3195' - 3295' atted between plugs. Installed customary $4\frac{1}{2}$ ' xillows:	llows:
Plugged and ab	pandoned May 17, 1965. Cement plugs set as for 10 sx at surface 25 sx 315' - 415' 25 sx 1420' - 1520' 25 sx 2800' - 2900' 25 sx 3195' - 3295' attend between plugs. Installed customary $4\frac{1}{2}$ ' xillows: Shoreline Exploration Co. #2 Snyder	llows:
Plugged and ab	pandoned May 17, 1965. Cement plugs set as for 10 sx at surface 25 sx 315' - 415' 25 sx 1420' - 1520' 25 sx 2800' - 2900' 25 sx 3195' - 3295' attend between plugs. Installed customary $4\frac{1}{2}$ ' xillows: Shoreline Exploration Co. #2 Snyder	llows:
Plugged and ab	pandoned May 17, 1965. Cement plugs set as for 10 sx at surface 25 sx 315' - 415' 25 sx 1420' - 1520' 25 sx 2800' - 2900' 25 sx 3195' - 3295' attend between plugs. Installed customary $4\frac{1}{2}$ ' xillows: Shoreline Exploration Co. #2 Snyder	llows:
Plugged and ab	pandoned May 17, 1965. Cement plugs set as for 10 sx at surface 25 sx 315' - 415' 25 sx 1420' - 1520' 25 sx 2800' - 2900' 25 sx 3195' - 3295' attend between plugs. Installed customary $4\frac{1}{2}$ ' xillows: Shoreline Exploration Co. #2 Snyder	llows:
Plugged and ab Haavy mud spo inscribed as fo	pandoned May 17, 1965. Cement plugs set as for 10 sx at surface 25 sx 315' - 415' 25 sx 1420' - 1520' 25 sx 2800' - 2900' 25 sx 3195' - 3295' atted between plugs. Installed customary $4\frac{1}{2}$ ' xillows: Shoreline Exploration Co. #2 Snyder SW $\frac{1}{4}$ SE $\frac{1}{4}$ Sec. 16, T. 20 S., R. 33 E.	llows:
Plugged and ab Haavy mud spo inscribed as fo	pandoned May 17, 1965. Cement plugs set as for 10 sx at surface 25 sx 315' - 415' 25 sx 1420' - 1520' 25 sx 2800' - 2900' 25 sx 3195' - 3295' attend between plugs. Installed customary $4\frac{1}{2}$ ' xillows: Shoreline Exploration Co. #2 Snyder	llows:
Plugged and ab Haavy mud spo inscribed as fo	pandoned May 17, 1965. Cement plugs set as for 10 sx at surface 25 sx 315' - 415' 25 sx 1420' - 1520' 25 sx 2800' - 2900' 25 sx 3195' - 3295' atted between plugs. Installed customary $4\frac{1}{2}$ ' x allows: Shoreline Exploration Co. #2 Snyder SW $\frac{1}{4}$ SE $\frac{1}{4}$ Sec. 16, T. 20 S., R. 33 E.	llows:
Plugged and ab Haavy mud spo inscribed as fo	pandoned May 17, 1965. Cement plugs set as for 10 sx at surface 25 sx 315' - 415' 25 sx 1420' - 1520' 25 sx 2800' - 2900' 25 sx 3195' - 3295' atted between plugs. Installed customary $4\frac{1}{2}$ ' xillows: Shoreline Exploration Co. #2 Snyder SW $\frac{1}{4}$ SE $\frac{1}{4}$ Sec. 16, T. 20 S., R. 33 E.	llows:
Plugged and ab Haavy mud spo inscribed as fo	pandoned May 17, 1965. Cement plugs set as for 10 sx at surface 25 sx 315' - 415' 25 sx 1420' - 1520' 25 sx 2800' - 2900' 25 sx 3195' - 3295' atted between plugs. Installed customary $4\frac{1}{2}$ ' x allows: Shoreline Exploration Co. #2 Snyder SW $\frac{1}{4}$ SE $\frac{1}{4}$ Sec. 16, T. 20 S., R. 33 E.	llows: 4' dry hole marker
Plugged and ab Haavy mud spo inscribed as fo	pandoned May 17, 1965. Cement plugs set as for 10 sx at surface 25 sx 315' - 415' 25 sx 1420' - 1520' 25 sx 2800' - 2900' 25 sx 3195' - 3295' atted between plugs. Installed customary $4\frac{1}{2}$ ' x allows: Shoreline Exploration Co. #2 Snyder SW $\frac{1}{4}$ SE $\frac{1}{4}$ Sec. 16, T. 20 S., R. 33 E.	llows: 4' dry hole marker
Plugged and ab Haavy mud spo inscribed as fo	pandoned May 17, 1965. Cement plugs set as for 10 sx at surface 25 sx 315' - 415' 25 sx 1420' - 1520' 25 sx 2800' - 2900' 25 sx 3195' - 3295' atted between plugs. Installed customary $4\frac{1}{2}$ ' x allows: Shoreline Exploration Co. #2 Snyder SW $\frac{1}{4}$ SE $\frac{1}{4}$ Sec. 16, T. 20 S., R. 33 E.	llows: 4' dry hole marker