## STATE OF NEW MEXICO ERGY AND MINERALS DEPARTMENT --. -- -----JIL CONSERVATION DIVISION DISTRIBUTION P. O. BOX 2088 SANTA PE Form C-103 . SANTA FE, NEW MEXICO 87501 Revised 10-1-78 FILE U.S.G.S. Sa. Indicate Type of Lease LAND OFFICE OPERATOR F. XX 5. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS 100 HOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OCCUPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. 100 HOT USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) WELL X 7. Unit Agreement Name me of Operator Chevron U.S.A. Inc. 8. Farm or Lease Name dress at Operator Graham St. (NCT-F) P.O. Box 670 Hobbs, NM 88240 9. Well No. 10. Field and Pool, or Wildcat South Eunice Monument G-SA 36E 15. Elevation (Show whether DF, RT, GR, etc.) 12. County 3589 Lea Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: RM REMEDIAL WORK PLUG AND ABANDON ARILY ASAHOOM COMMENCE ORILLING OPHS. . OR ALTER CASING CHANGE PLANE TA wellbore Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed Work performed 4-18-88 thru 4-19-88 POOH w/ production equipment. Ran gauge ring to 3700'. Set CIBP at 3650'. Dumped 35' cmt on CIBP. TIH w/ tbg to 3610'. Circ. well w/pkr fluid. LD prod. tbg. finish loading csg w/pkr fluid. ND BOP, NU flange. Install swage and 2" valve. RD MO pulling unit. Clean off location. Well TA'd.

Orig. Signed by
Paul Kautz

Geologist

Title

Part Geologist

Part Geologist