TRADUTION	NEW MEXICO OIL CONS	ERVATION COMMISSION	Form C -103 Supersedes Old C-102 and C-103 Effective 1-1-65
U.S.G.S.]		5a. Indicate Type of Lease
LAND OFFICE			State Fee X
OPERATOR	J		5. State Oil & Gas Lease No.
		•	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)			
			7. Unit Agreement Name
WELL WELL OTHER Exploratory well for oil or gas.			
2. Name of Operator			8. Farm or Lease Name
Clayton W. Williams, Jr.			Perla
3. Address of Operator			9. Well No.
One Spring Drive, Fort Stockton, Texas 79735			1
			10. Field and Pool, or Wildcat
UNIT LETTER J 2,310' FEET FROM THE SOUTH LINE AND 980' FEET FROM			Wildcat
THE <u>East</u> line, section <u>19</u> township <u>19</u> Range <u>36</u> E NMPM.			
15. Elevation (Show whether DF, RT, GR, etc.)			12. County
All IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII			Lea
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OF ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		OTHER	
OTHER			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled $6\frac{1}{2}$ " hole from 11,230' to 13,065'. Circulated samples for $4\frac{1}{2}$ hours. Pulled out of the hole. Ran Gamma Ray - Sonic - Dual Induction and Dip Meter Log from 13,060' Wire Line Total Depth to 11,200'. Went in the hole with drill pipe - circulated for 4 hours. Pulled out of the hole. Rigged up and ran 52 jts 2,160.37' of $5\frac{1}{2}$ " OD, 23 lb/ft, C-75, Hydril SFJ-P casing. Overall length including liner hanger and float equipment 2,173.55'. Went in the hole and set liner at 13,063'. Circulated $\frac{1}{2}$ hour. Cemented with 100 sx Howco Lite Wate cement containing 1% CFR2, 3 pounds per sack KCL and $\frac{1}{2}$ pound per sack Flocele. Bumped plug with 2,000 psi. Job complete @ 11:30 PM 12-4-73. Pulled out of the hole and waited on cement a total of 24 hours. Went in the hole with $6\frac{1}{2}$ " bit to 10,805'. Washed 86' to the top of liner at 10,891'. No cement at the top of liner. Circulated 3 hours. Displaced Fresh Water Mud with Fresh Water. Pressure tested liner to 2,000 psi. Pulled out of the hole, picked up $4\frac{1}{2}$ " OD Mill and went in the hole to top of cement @ 12,923'. Pressure tested liner to 2,000 psi. Drilled landing collar, float collar, and 79' cement inside liner to 13,063'. Drilled float shoe and washed 2' to bottom at 13,065'. Circulated 3 hours. Pulled out of the hole, picked up $4\frac{1}{2}$ " bit, went in the hole and continued drilling $4\frac{1}{2}$ " hole.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

TITLE

Agent

1 - 29 - 74DATE

DAT

APPROVED BY