(May 1963) UNIT STATES DEPARTMENT OF THE INTER	SUBMIT IN UNITHIC (Other inscructions o RIOR verse side)	1. a.: D	orm approved, udget Bureau No.	42-R1424.
GEOLOGICAL SURVEY			ESIGNATION AND S	ERIAL NO.
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)		6. IF INDIA	LC 065658 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
Use "APPLICATION FOR PERMIT_" for such	proposals.)			
WELL CAS WELL OTHER		7. UNIT AG	REEMENT NAME	
2. NAME OF OPERATOR		Teas	Teas Yates Unit	
Anadarko Production Company		1	t No. 5	
3. ADDRESS OF OPERATOR		9. WELL NO		
LOCATION OF WELL (Report logation slow-ly and	88231		5	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		10, FIELD A	10, FIELD AND POOL, OR WILDCAT	
990' FNL and 990' FWL		Teas 11. sec., T., SURV	Yates R., M., OR BLK. AN EY OR AREA	D
4. PERMIT NO.		14-02	0S-R33E	
15. ELEVATIONS (Show whether)	DF, RT, GR, etc.)	12. COUNTY	OB PARISH 13. S	TATE
Date issued 5-6-74 3570' GR		Lea		Mexic
6. Check Appropriate Box To Indicate	Nature of Notice, Report.	or Other Data		
NOTICE OF INTENTION TO:		BSEQUENT REPORT (
TEST WATER SHUT-OFF PULL OR ALTER CASING	WATEL SHUT-OFF			г- -
FRACTURE TREAT MULTIPLE COMPLETE	FRACTURE TREATMENT		EPAIRING WELL LTERING CASING	;
SHOOT OR ACIDIZE ABANDON*	SHOOTING OR ACIDIZING		BANDON MENT*	
REPAIR WELL CHANGE PLANS (Other)	(Other) Commence	<u>e Drillin</u>	q '	'
7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertine proposed work. If well is directionally drilled, give subsurface loce nent to this work.) •	(NOTE: Report res Completion or Rec	OMDICION KEYNET S	ni Lor fam.)	
Moved in and rigged up Cactus Dril Spud w/12¼" bit @ 6:30 PM 7-9-74. Drilled 12¼" hole to 1424'. Ran 1410' 9-5/8" 32# J-55 Casing . Cemented using 360 sks Class "C"	Set at 1420			
Spud w/124" bit @ 6:30 PM 7-9-74. Drilled 124" hole to 1424'. Ran 1410' 9-5/8" 32# J-55 Casing . Cemented using 360 sks. Class "C" per sk & 4# cello-flakes per sk, f with 2% cacl, 10# salt per sack ar 140 sks to fit. Plug down @ 6:30 Shut in waiting on cment 24 hours.	Set at 1420'. cement with 4% of collowed by 200 and $\frac{1}{2}$ cello-flake PM 7-11-74	gel, 2% ca sks Class es per sk.	"C" ceme . Circul	nt ated
Spud w/124" bit @ 6:30 PM 7-9-74. Drilled 124" hole to 1424'. Ran 1410' 9-5/8" 32# J-55 Casing . Cemented using 360 sks. Class "C" per sk & 4# cello-flakes per sk, f with 2% cacl, 10# salt per sack ar 140 sks to fit. Plug down @ 6:30 Shut in waiting on cment 24 hours. minutes without loss of pressure.	Set at 1420'. cement with 4% of collowed by 200 and $\frac{1}{2}$ cello-flake PM 7-11-74	gel, 2% ca sks Class es per sk.	"C" ceme . Circul	nt ated
Spud w/12¼" bit @ 6:30 PM 7-9-74. Drilled 12¼" hole to 1424'. Ran 1410' 9-5/8" 32# J-55 Casing . Cemented using 360 sks. Class "C" per sk & ¼# cello-flakes per sk, f with 2% cacl, 10# salt per sack ar 140 sks to fit. Plug down @ 6:30 Shut in waiting on cment 24 hours.	Set at 1420'. cement with 4% of collowed by 200 and $\frac{1}{2}$ cello-flake PM 7-11-74	gel, 2% ca sks Class es per sk.	"C" ceme . Circul	nt ated
Spud w/124" bit @ 6:30 PM 7-9-74. Drilled 124" hole to 1424'. Ran 1410' 9-5/8" 32# J-55 Casing . Cemented using 360 sks. Class "C" per sk & 4# cello-flakes per sk, f with 2% cacl, 10# salt per sack ar 140 sks to fit. Plug down @ 6:30 Shut in waiting on cment 24 hours. minutes without loss of pressure.	Set at 1420'. cement with 4% of collowed by 200 and $\frac{1}{2}$ cello-flake PM 7-11-74	gel, 2% ca sks Class es per sk.	"C" ceme . Circul	nt ated
Spud w/124" bit @ 6:30 PM 7-9-74. Drilled 124" hole to 1424'. Ran 1410' 9-5/8" 32# J-55 Casing . Cemented using 360 sks. Class "C" per sk & 4# cello-flakes per sk, f with 2% cacl, 10# salt per sack ar 140 sks to fit. Plug down @ 6:30 Shut in waiting on cment 24 hours. minutes without loss of pressure.	Set at 1420'. cement with 4% of collowed by 200 and $\frac{1}{2}$ cello-flake PM 7-11-74	gel, 2% ca sks Class es per sk.	"C" ceme . Circul	nt ated
Spud w/124" bit @ 6:30 PM 7-9-74. Drilled 124" hole to 1424'. Ran 1410' 9-5/8" 32# J-55 Casing . Cemented using 360 sks. Class "C" per sk & 4# cello-flakes per sk, f with 2% cacl, 10# salt per sack ar 140 sks to fit. Plug down @ 6:30 Shut in waiting on cment 24 hours. minutes without loss of pressure.	Set at 1420'. cement with 4% of collowed by 200 and $\frac{1}{2}$ cello-flake PM 7-11-74	gel, 2% ca sks Class es per sk.	"C" ceme . Circul	nt ated
Spud w/124" bit @ 6:30 PM 7-9-74. Drilled 124" hole to 1424'. Ran 1410' 9-5/8" 32# J-55 Casing . Cemented using 360 sks. Class "C" per sk & 4# cello-flakes per sk, f with 2% cacl, 10# salt per sack ar 140 sks to fit. Plug down @ 6:30 Shut in waiting on cment 24 hours. minutes without loss of pressure.	Set at 1420'. cement with 4% of collowed by 200 and $\frac{1}{2}$ cello-flake PM 7-11-74	gel, 2% ca sks Class es per sk.	"C" ceme . Circul	nt ated
Spud w/12¼" bit @ 6:30 PM 7-9-74. Drilled 12¼" hole to 1424'. Ran 1410' 9-5/8" 32# J-55 Casing . Cemented using 360 sks. Class "C" per sk & ¼# cello-flakes per sk, f with 2% cacl, 10# salt per sack ar 140 sks to fit. Plug down @ 6:30 Shut in waiting on cment 24 hours. minutes without loss of pressure.	Set at 1420'. cement with 4% of collowed by 200 and $\frac{1}{2}$ cello-flake PM 7-11-74	gel, 2% ca sks Class es per sk.	"C" ceme . Circul	nt ated
Spud w/12¼" bit @ 6:30 PM 7-9-74. Drilled 12¼" hole to 1424'. Ran 1410' 9-5/8" 32# J-55 Casing . Cemented using 360 sks. Class "C" per sk & ¼# cello-flakes per sk, f with 2% cacl, 10# salt per sack ar 140 sks to fit. Plug down @ 6:30 Shut in waiting on cment 24 hours. minutes without loss of pressure.	Set at 1420'. cement with 4% of collowed by 200 and $\frac{1}{2}$ cello-flake PM 7-11-74	gel, 2% ca sks Class es per sk.	"C" ceme . Circul	nt ated
Spud w/124" bit @ 6:30 PM 7-9-74. Drilled 124" hole to 1424'. Ran 1410' 9-5/8" 32# J-55 Casing . Cemented using 360 sks. Class "C" per sk & ½# cello-flakes per sk, f with 2% cacl, 10# salt per sack ar 140 sks to rit. Plug down @ 6:30 Shut in waiting on cment 24 hours. minutes without loss of pressure. Drilling ahead with 8-3/4" bit.	Set at 1420'. cement with 4% of collowed by 200 and $\frac{1}{2}$ cello-flake PM 7-11-74	gel, 2% ca sks Class es per sk.	"C" ceme . Circul	nt ated
Spud w/124" bit @ 6:30 PM 7-9-74. Drilled 124" hole to 1424'. Ran 1410' 9-5/8" 32# J-55 Casing . Cemented using 360 sks. Class "C" per sk & ¼# cello-flakes per sk, f with 2% cacl, 10# salt per sack ar 140 sks to fit. Plug down @ 6:30 Shut in waiting on cment 24 hours. minutes without loss of pressure. Drilling ahead with 8-3/4" bit.	Set at 1420'. cement with 4% of collowed by 200 and $\frac{1}{2}$ cello-flake PM 7-11-74	gel, 2% ca sks Class es per sk.	"C" ceme . Circul	nt ated
Spud w/124" bit @ 6:30 PM 7-9-74. Drilled 124" hole to 1424'. Ran 1410' 9-5/8" 32# J-55 Casing . Cemented using 360 sks. Class "C" per sk & ½# cello-flakes per sk, f with 2% cacl, 10# salt per sack ar 140 sks to rit. Plug down @ 6:30 Shut in waiting on cment 24 hours. minutes without loss of pressure. Drilling ahead with 8-3/4" bit.	Set at 1420'. cement with 4% of collowed by 200 and ½# cello-flake PM 7-11-74. Tested casing	gel, 2% ca sks Class es per sk to 600 pa	"C" ceme Circul si for 30	nt ated
Spud w/124" bit @ 6:30 PM 7-9-74. Drilled 124" hole to 1424'. Ran 1410' 9-5/8" 32# J-55 Casing . Cemented using 360 sks. Class "C" per sk & ½# cello-flakes per sk, f with 2% cacl, 10# salt per sack an 140 sks to pit. Plug down @ 6:30 Shut in waiting on cment 24 hours. minutes without loss of pressure. Drilling ahead with 8-3/4" bit. I hereby certify that the foregoing is true and correct SIGNED	Set at 1420'. cement with 4% of collowed by 200 and ½# cello-flake PM 7-11-74. Tested casing	gel, 2% ca sks Class es per sk to 600 pa	"C" ceme Circul si for 30	nt ated
Spud w/124" bit @ 6:30 PM 7-9-74. Drilled 124" hole to 1424'. Ran 1410' 9-5/8" 32# J-55 Casing . Cemented using 360 sks. Class "C" per sk & ½# cello-flakes per sk, f with 2% cacl, 10# salt per sack an 140 sks to pit. Plug down @ 6:30 Shut in waiting on cment 24 hours. minutes without loss of pressure. Drilling ahead with 8-3/4" bit. I hereby certify that the foregoing is true and correct SIGNED	Set at 1420'. cement with 4% of collowed by 200 and ½# cello-flake PM 7-11-74. Tested casing	gel, 2% ca sks Class es per sk to 600 pa	"C" ceme Circul si for 30	nt ated
Spud w/124" bit @ 6:30 PM 7-9-74. Drilled 124" hole to 1424'. Ran 1410' 9-5/8" 32# J-55 Casing . Cemented using 360 sks. Class "C" per sk & ½# cello-flakes per sk, f with 2% cacl, 10# salt per sack an 140 sks to pit. Plug down @ 6:30 Shut in waiting on cment 24 hours. minutes without loss of pressure. Drilling ahead with 8-3/4" bit. I hereby certify that the foregoing is true and correct SIGNED	Set at 1420'. cement with 4% of collowed by 200 and ½# cello-flake PM 7-11-74. Tested casing	gel, 2% ca sks Class es per sk to 600 pa	"C" ceme Circul si for 30	nt ated
Spud w/124" bit @ 6:30 PM 7-9-74. Drilled 124" hole to 1424'. Ran 1410' 9-5/8" 32# J-55 Casing . Cemented using 360 sks. Class "C" per sk & ¼# cello-flakes per sk, f with 2% cacl, 10# salt per sack ar 140 sks to rit. Plug down @ 6:30 Shut in waiting on cment 24 hours. minutes without loss of pressure. Drilling ahead with 8-3/4" bit. I hereby certify that the foregoing is true and correct SIGNED	Set at 1420'. cement with 4% of collowed by 200 s ad ½# cello-flake PM 7-11-74. Tested casing rea Supervisor	gel, 2% ca sks Class es per sk to 600 ps DATE	"C" ceme Circul si for 30	nt ated