

N.O. OF COPIES RECEIVED

DISTRIBUTION

SANTA FE

FILE

U.S.G.S.

LAND OFFICE

OPERATOR

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease

State ☐

Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CLEAN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒

GAS WELL ☐

OTHER ☐

1. Name of Operator

Atlantic Richfield Company

2. Address of Operator

P.O. Box 1710, Hobbs, New Mexico 88240

3. Location of Well

UNIT LETTER C 990 FEET FROM THE North LINE AND 1650 FEET FROM THE West LINE, SECTION 31 TOWNSHIP 19S RANGE 37E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

J. R. Phillips "B"

9. Well No.

6

10. Field and Pool, or Wildcat
Eunice Monument
Grayburg San Andres

11. Elevation (Show whether DF, RT, GR, etc.)

3605.3' GR

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER Cmt Squeeze 5-1/2" Prod Csg ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to cmt squeeze 5-1/2" OD Production Csg & shut off pressure flow on 8-5/8" x 5-1/2" annulus in the following manner:

1. Rig up, POH w/rods & pump. Install BOP and POH w/tbg assy.
2. RIH w/FBRC & RBP, set BP @ approx. 3700' cap w/5 sx sd. Pressure test 5-1/2" csg 0-3700'.
3. Run CBL, locate TOC, perf 2' w/2JSPF.
4. RIH w/FBRC/cmt retr, set approx 150' above squeeze holes, cmt squeeze w/volume as required. WOC.
5. POH w/cmt tools. Drill out cmt & pressure test squeeze job or csg holes.
6. RO sand off RBP & retrieve BP.
7. RIH w/tbg assy, rod & pump, return to production.

THIS DOCUMENT IS UNCLASSIFIED
DATE 10-10-2001 BY 1045 GAO/ELC

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature]

TITLE Dist. Drlg. Supt.

DATE 12-18-78

APPROVED BY Jerry Seaton

TITLE Dist. J. Supv.

DATE DEC 18 1978

CONDITIONS OF APPROVAL, IF ANY: