. COPIES RECEIVED		Form C-103
TRIBUTION		Supersedes Old C-102 and C-103
FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		
U.S.G.S.		State X Fee
OPERATOR		State A Fee 5. State Oil & Gas Lease No.
OF ENATOR	J	B-1431
SLINIDA	DY NOTICES AND DEPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PRO USE **APPLICAT	RY NOTICES AND REPORTS ON WELLS DESSALS TO DRILL OF TO DEEPEN OF PLUG BACK TO A DIFFERENT RESERVOIR. 10h FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)	
1.		7. Unit Agreement Name
OIL X GAS WELL	OTHER-	
2, Name of Operator		8. Farm or Lease Name
John H. Hendrix 3. Address of Operator		State T
•	W.111 m	9. Well No.
4. Location of Well	, Midland, Texas 79701	8
V	1650	, " " " "
UNIT LETTER,	1650 FEET FROM THE SOUTH LINE AND 1650 FEE	Eunice-Monument
THE West Line Section	on 28 TOWNSHIP 19-South RANGE 37-E	
THE WEST LINE, SECTION	ON 20 TOWNSHIP 19-BOULII RANGE 37-E	_NMPM. ()
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3590.7'	Lea
Check A	Appropriate Box To Indicate Nature of Notice, Report	or Other Data
		QUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	x
OTHER	OTHER	
OTHER		
17. Describe Proposed or Completed Op	Detations (Clearly state all pertinent details, and give pertinent dates, in	cluding estimated date of starting any proposed
		cluding estimated date of starting any proposed
17. Describe Proposed or Completed Op work) SEE RULE 1103.		cluding estimated date of starting any proposed
17. Describe Proposed or Completed Opwork) SEE RULE 1103. 1. Reached TD @ 4320	perations (Clearly state all pertinent details, and give pertinent dates, income on 12-19-74 (MST).	cluding estimated date of starting any proposed
17. Describe Proposed or Completed Opwork) SEE RULE 1103. 1. Reached TD @ 4320	perations (Clearly state all pertinent details, and give pertinent dates, in	cluding estimated date of starting any proposed
17. Describe Proposed or Completed Opwork) SEE RULE 1103. 1. Reached TD @ 4320 2. Ran 131 jts. 4-1/ 3. Cemented w/200 sx	Detations (Clearly state all pertinent details, and give pertinent dates, income of the control	sxs. Class "C"
17. Describe Proposed or Completed Opwork) SEE RULE 1103. 1. Reached TD @ 4320 2. Ran 131 jts. 4-1/ 3. Cemented w/200 sx 50-50 pozmix, 8%	perations (Clearly state all pertinent details, and give pertinent dates, in 0' on 12-19-74 (MST). 2" csg. set @ 4319'. 2s. "lite" wt, 15% salt, 1/4# flocel and 225 salt and 2% gel. Plug down @ 6:45 p.m. (MS	sxs. Class "C" T) 12-19-74.
17. Describe Proposed or Completed Opwork) SEE RULE 1103. 1. Reached TD @ 4320 2. Ran 131 jts. 4-1/ 3. Cemented w/200 sx 50-50 pozmix, 8%	Detations (Clearly state all pertinent details, and give pertinent dates, income of the control	sxs. Class "C" T) 12-19-74.
17. Describe Proposed or Completed Opwork) SEE RULE 1103. 1. Reached TD @ 4320 2. Ran 131 jts. 4-1/ 3. Cemented w/200 sx 50-50 pozmix, 8% 4. West Engineering	perations (Clearly state all pertinent details, and give pertinent dates, in 0' on 12-19-74 (MST). 2" csg. set @ 4319'. 2s. "lite" wt, 15% salt, 1/4# flocel and 225 salt and 2% gel. Plug down @ 6:45 p.m. (MS	sxs. Class "C" T) 12-19-74.
17. Describe Proposed or Completed Opwork) SEE RULE 1103. 1. Reached TD @ 4320 2. Ran 131 jts. 4-1/ 3. Cemented w/200 sx 50-50 pozmix, 8% 4. West Engineering	Detations (Clearly state all pertinent details, and give pertinent dates, income of the state of	sxs. Class "C" T) 12-19-74.
17. Describe Proposed or Completed Opwork) SEE RULE 1103. 1. Reached TD @ 4320 2. Ran 131 jts. 4-1/ 3. Cemented w/200 sx 50-50 pozmix, 8% 4. West Engineering	Detations (Clearly state all pertinent details, and give pertinent dates, income of the state of	sxs. Class "C" T) 12-19-74.
17. Describe Proposed or Completed Opwork) SEE RULE 1103. 1. Reached TD @ 4320 2. Ran 131 jts. 4-1/ 3. Cemented w/200 sx 50-50 pozmix, 8% 4. West Engineering	Detations (Clearly state all pertinent details, and give pertinent dates, income of the state of	sxs. Class "C" T) 12-19-74.
17. Describe Proposed or Completed Opwork) SEE RULE 1103. 1. Reached TD @ 4320 2. Ran 131 jts. 4-1/ 3. Cemented w/200 sx 50-50 pozmix, 8% 4. West Engineering	Detations (Clearly state all pertinent details, and give pertinent dates, income of the state of	sxs. Class "C" T) 12-19-74.
17. Describe Proposed or Completed Opwork) SEE RULE 1103. 1. Reached TD @ 4320 2. Ran 131 jts. 4-1/ 3. Cemented w/200 sx 50-50 pozmix, 8% 4. West Engineering	Detations (Clearly state all pertinent details, and give pertinent dates, income of the state of	sxs. Class "C" T) 12-19-74.
17. Describe Proposed or Completed Opwork) SEE RULE 1103. 1. Reached TD @ 4320 2. Ran 131 jts. 4-1/ 3. Cemented w/200 sx 50-50 pozmix, 8% 4. West Engineering	Detations (Clearly state all pertinent details, and give pertinent dates, income of the state of	sxs. Class "C" T) 12-19-74.
17. Describe Proposed or Completed Opwork) SEE RULE 1103. 1. Reached TD @ 4320 2. Ran 131 jts. 4-1/ 3. Cemented w/200 sx 50-50 pozmix, 8% 4. West Engineering	Detations (Clearly state all pertinent details, and give pertinent dates, income of the state of	sxs. Class "C" T) 12-19-74.
17. Describe Proposed or Completed Opwork) SEE RULE 1103. 1. Reached TD @ 4320 2. Ran 131 jts. 4-1/ 3. Cemented w/200 sx 50-50 pozmix, 8% 4. West Engineering 5. WOC 18 hrs. Test	perations (Clearly state all pertinent details, and give pertinent dates, in on 12-19-74 (MST). 2" csg. set @ 4319'. 2s. "lite" wt, 15% salt, 1/4# flocel and 225 salt and 2% gel. Plug down @ 6:45 p.m. (MS ran temperature survey. Found cement top @ ed to 700#. Tested ok.	sxs. Class "C" T) 12-19-74.
17. Describe Proposed or Completed Opwork) SEE RULE 1103. 1. Reached TD @ 4320 2. Ran 131 jts. 4-1/ 3. Cemented w/200 sx 50-50 pozmix, 8% 4. West Engineering 5. WOC 18 hrs. Test	Detations (Clearly state all pertinent details, and give pertinent dates, income of the state of	sxs. Class "C" T) 12-19-74.
17. Describe Proposed or Completed Opwork) SEE RULE 1103. 1. Reached TD @ 4320 2. Ran 131 jts. 4-1/ 3. Cemented w/200 sx 50-50 pozmix, 8% 4. West Engineering 5. WOC 18 hrs. Test	perations (Clearly state all pertinent details, and give pertinent dates, in on 12-19-74 (MST). 2" csg. set @ 4319'. 2s. "lite" wt, 15% salt, 1/4# flocel and 225 salt and 2% gel. Plug down @ 6:45 p.m. (MS ran temperature survey. Found cement top @ ed to 700#. Tested ok.	sxs. Class "C" T) 12-19-74.

CONDITIONS OF APPROVAL, IF ANY: