

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-24997
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. v-2770
7. Lease Name or Unit Agreement Name Hanson State
8. Well No. 1
9. Pool name or Wildcat Wildcat <i>Merran</i>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3534 Gr

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator C. W. Trainer
3. Address of Operator c/o Oil Reports & Gas Services, Inc., PO Box 755, Hobbs, NM 88241-0755
4. Well Location Unit Letter <u>N</u> : <u>660</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>13</u> Township <u>20S</u> Range <u>32E</u> NMPM <u>Lea</u> County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/30/93 MIRU; begin work
12/1-4/93 TOH w/tbg; mill out tight spot @ 1115'-1145'
12/5/93 Tag top of fish @ 10, 683'. Attempt to pull fish.
12/9/93 Tag fish @ 10,683'; pulled fish. Pressure up 9 5/8" csg to 1000#, no bleed-off.
SION w/csg on vac.
12/10/93 Set RBP @ 2000' w/3 sx sand on top. Pmp 250 sx "C" w/3% CaCl2. Displace w/H2O; after 14 bbls cnt circ out 9 5/8". Close 9 5/8" valve; cont H2O displacement; total 35 bbls. TOC est. @ 850'. Press up from 200# to 1500#. No leakoff. Leave on pressure overnight.
12/13/93 Tag TOC @ 929'. DO cnt; tst 7" to 2500# for 30min., tst OK. Wash sand & TOH w/ RBP.

REPORT TO CONTINUE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Laren Holler* TITLE Agent DATE 3/1/94
TYPE OR PRINT NAME Laren Holler TELEPHONE NO. (505) 393-2727

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

MAR 09 1994

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: