

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-70

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator AMOCO PRODUCTION COMPANY	8. Farm or Lease Name South Hobbs (GSA) Unit
3. Address of Operator P. O. BOX 68 HOBBS, NEW MEXICO 88240	9. Well No. 123
4. Location of Well UNIT LETTER <u>H</u> <u>2390</u> FEET FROM THE <u>North</u> LINE AND <u>150</u> FEET FROM THE <u>East</u> LINE, SECTION <u>6</u> TOWNSHIP <u>19-S</u> RANGE <u>38-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Hobbs GSA
15. Elevation (Show whether DE, RT, GR, etc.) 3619.9' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to reduce water production as follows:
MISU and POH w/ rods, pump, and tubing. RIH w/ CIBP and set at 4185'. Cap CIBP w/ 15'
of Cal Seal. (New PBD 51B 4170'.) Re-run the production equipment and land
the seating nipple at 4150'. Return well to production.

0+5 NMOC-D-11-JRB 1-FJN 1-CMH

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Charles M. Serrano</u>	TITLE <u>ADMINISTRATIVE ANALYST (SG)</u>	DATE <u>1-16-86</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR		
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

JAN 20 1986

RECEIVED

JAN 17 1986

O.C.D.
HOBBS OFFICE