DRILLING, WORKOVERS & PRODUCTION DATA

OSUDO, WEST

Perfs

Watkins "B" Gas Com #1

Lea County, NM TD: 13,500' PBTD: 13,500

13,169-210 13,392-400'

AFE/LW: B7022/06288-01 WI: 57.246%

16" @ 431'

10¾" @ 4310' 7%" @ 11,456'

4½" Inr 10,344-12,995' Open Hole 12,995-13,500'

AFE: \$60,000

OBJECTIVE:

Workover in the Morrow

DATE: 11/18/97

DC: \$ 1450 CUM: \$ 65100

Activity:

Daily Details:

RU SWAB. IFL-8400'. MADE 7 SWAB RUNS. REC'D 12 BW. FFL-13,200'. CWI. RD DAWSON PU.

Fluid to Rec 180

Rec Today 12

Cum Rec 60

Left to Rec 120

DATE: 11/19/97

DC: \$ 350 CUM: \$ 65450

Activity:

Daily Details:

28-HR SITP-1200 PSI. TURNED WELL TO LINE ON 10/64" CK. RU RAMSWAB UNIT. SWAB UNIT BROKE DOWN.

Fluid to Rec 180

Rec Today 12

Cum Re 60

Left to Rec 120

DATE: 11/20/97

DC: \$ 950 CUM: \$ 66400

Activity:

Daily Details:

F-14, TP-80 PSI, CP-0 PSI, 62 MCF, 0 BO, 0 B. BLEW WELL DOWN. FU SWAB. IFL-4800'. SCATTERED LIGHT

FLUID. MADE 8 RUNS REC'D 15 BBW. TURNED WELL DOWNLING ON 10/64" CK. SDFN.

Fluid to Rec

180

Rec Today 15

Cım Rec 75

Left to Rec

105

DATE: 11/21/97

DC: \$ 1450 CUM: \$ 67850

Activity:

Daily Details:

F-15, TP-60 PSI, CP-0 PSI, 141 MCF, 0 BO, 0 BW. BLEW WELL DOWN. RU SWAB. IFL-12,100'. SCATTERED LT FLUID. MADE I SWAB RUN. WENT TO HRLY RUNS. MADE 5 ADD'L RUNS. SWABBED BACK 5 BW. TURNED WELL DOWN LINE @ 30/64" CK. RDMOL.

Fluid to Rec

180

Rec Today

Cum Rec 80

Left to Rec 100

DATE: 11/22-23/97

DC:\$ 0 CUM:\$ 67850

Activity: Daily Details:

F-24, 30/64" CK, FTP-60 PSI, 209 MCF, 5 BO, 9 BW, CP-40PSI. LINE PRESSURE-48 PSI.

F-24, 30/64" CK, FTP-80 PSI, 217 MCF, 4 BO, 6 BW, CP-6(PSI. LINE PRESSURE-53 PSI. FINAL REPORT.