HALLIBURTON SERVICES MIDLAND DIVISION HOBBS, NEW MEXICO 88240

Ticket No. 116080

	LABORATORY	WATER ANALYSIS	No. <u>W81-266</u>
Jake L. Hamon			Date3-26-81
	ational Bank Tower	This report i it nor any p or disclosed of laborator course of re	s the property of Halliburton Company and neithe part thereof nor a copy thereof is to be published without first securing the express written approva y management; it may however, be used in the gular business operations by any person or concern sets thereof receiving such report from Halliburton
ubmitted by		······································	Date Rec3_26_81
Vell No <u>. Amerada Fed</u> e	eral #3 Depth	8745-8780*	Formation Bone Spring
CountyLea	Field W.C.		SourceDST #1
	Sampler	Top of Recover	y Pit Sample
esistivity	0.076 @ 74°F.	0.076 @ 74°F.	0.076 @ 74°F.
pecific Gravity			
н			
alcium (Ca)			*MP
lagnesium (Mg)			<u></u>
hlorides (Cl)	90,000	90,000	90,000
ulfates (SO4)	·	<u></u>	
icarbonates (HCO <sub>3</sub> )			
oluble Iron (Fe)			
		·	
emarks:			*Milligrams per liter
•			
	Respect	fully submitted,	
Analyst:Brewer		_ НА	LLIBURTON COMPANY
: <b>c</b> : .		P	W. L. Burg

This report is limited to the described sample tested. Any user of this report agrees that halliburton shall /7 not be liable for any LOSS or damage, whether it be to act or omission, resulting from such report or its use.