## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION	
BANTA PE	
FILE	
U.S.G.S.	
LAND OFFICE	 
OPERATOR	1

## OIL CONSERVATION DIVISION

POITUBIRTZIO	P. O. BOX 2088	Form C-103 Revised 19-1-78
SANTA PE	SANTA FE, NEW MEXICO 87501	5a. Indicate Type of Lease
U.S.O.S.	1	
LAND OFFICE	1 .	
OPERATOR	]	5. State Oil & Gas Lease No.
		mmmmm <del>m-</del>
SUNDR	RY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PRO USE "APPLICAT	OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. TION FOR PERMIT -** (FORM C-101) FOR SUCH PROPOSALS.)	
1.		7. Unit Agreement Name
WELL WELL WELL	OTHER.	0.5
Name of Operator		8. Farm or Lease Name
Ike Lovelady, Inc. (PETROMARK RESOURCES COMPANY)		<u> McNeill</u>
3. Address of Operator		9. Well No.
P.O. Drawer 2666, Midland, Texas 79702		/
4. Location of Well		10. Field and Pool, or Wildcot Undesignated GP
UNIT LETTER M 660 FEET FROM THE West LINE AND 660 FEET		LET FROM
South	19-S RANGE 38-E	_ NMPM. (
THE		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
	Gr. 3,594	Lea /////////
i6. Check	Appropriate Box To Indicate Nature of Notice, Report	or Other Data
		QUENT REPORT OF:
NOTICE OF I		
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
i i i i i i i i i i i i i i i i i i i	COMMENCE DESLLING OPHS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS CASING TEST AND CEMENT JOB	
PULL OR ALTER CABING	OTHER	Π
OTHER		
17. Describe Proposed or Completed O	perations (Clearly state all pertinent details, and give pertinent dates, i	ncluding estimated date of starting any proposed
work) SEE RULE 1103.		
1	2 0001	
1. Set C.I.B.P. @	2,800°	
	ith tubing & tagged C.I.B.P.	
	e with 10#/gal. salt gel.	
4. Set 10sx. plug	2,800 -2,700 .	
5. Set 20sx. plug		
6. Set 10sx. plug at surface.		
7. Installed dry	noie marker.	
Work commenced 11,	/8/85	
Work completed 11,		•
	ed and ready for inspection	
	· ·	
10. I have be perfect that the information	n above is true and complete to the best of my knowledge and belief.	

JAN 2 3 1986

HOW 1985