STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES ACCEIVED	 ·
DISTRIBUTION	
SANTA FE	
FILE	 <u> </u>
U.S.G.S.	
LAND OFFICE	 <u> </u>

CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION

	DISTRIBUTE		-					Form C-103		
	SANTA FE		ر ا	P. O. BO			•	Revised 10-1-7		
	FILE			SANTA FE, NEV						
			1	D-P.O. Box 198	0 1-Fe	oreman	5a. India	cate Type of Lease		
	U.S.G.S.		Hobb:	s, NM 88240	1-F:	ile	State	X Foe		
	DERATOR		1-Engr	DW			L	Oil & Gas Lease No.		
	OPERATOR		1	.TechBB			J. Blate	On a day Lease No.		
							I	-6726		
		SUNDR	RY NOTICES A	AND REPORTS ON	WELLS					
	HT 3EU TON 00)	IS FORM FOR PRO	OPOSALS TO DRILL	OR TO DEEPEN OF PLUG	BACK TO A DIFFEREN	IT RESERVOIR.				
1.				· · · · · · · · · · · · · · · · · · ·			7. Unit	Agreement Name		
	OIL X	GAS								
<u></u>	***************************************	WELL L	OTHER-							
2. 1	lame of Operator						8. Form	or Lease Name		
	Getty Oi	.1 Company					Lv	Lynch 36 State		
3. A	ddress of Operator						9. Well			
	P.O. Box	730 Hobb	s, NM 882	40				1		
4 1	ocation of Well					*	10 Ftal	d and Pool, or Wildcat		
1			•				i	d and Pool, or wrided		
	UNIT LETTERE	·	1980 , , , ,	FROM THE North	LINE AND 6	50 FEE	T FROM Und	lesignated		
1										
	West		36	тоwnship20		21-₽				
	THE THOSE	LINE, SECTI	ON	TOWNSHIPZU	TS RANGE	24-F	HMPM.			
77	mmm	mm	777777	Nevation (Show whether	DE PT CP			<i></i>		
111			/////// 13. g	isvisadi dionel nombrei	Dr, KI, GK, etc.	,	12. Cou	31A ([[]]]]]		
77	777777777	7777777	7///// 3.	746.6 GL			Lea			
16.		Check	Appropriate 1	Box To Indicate 1	Varure of Noti	ce Robort	or Other Date			
	\$1 /		NTENTION TO		tacure of Most					
		OTICE OF II	NIENTION I	J:	1	SUBSEQ	UENT REPOI	RT OF:		
							_			
761	RFORM REMEDIAL WOR	K [PLUG AND ABANDON	REMEDIAL WORK	L_	_]	ALTERING CASING		
TE	MPORARILY ABANDON	П			COMMENCE DRILL	ING DENS	j	PLUG AND ABANDOHMENT		
	LL OR ALTER CABING	Ħ		CHANGE PLANS	1		₫.	PEGG NAG NONMER!		
,,,,	LE ON ACIEN CASING	LJ		CHANGE PLANS	CASING TEST AND	_	X	_		
				<u> </u>	OTHER			L		
	OTHER				\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	•	•			
			(0)							
17.	work) SEE RULE 1	or Completed Op 103.	perations (Clearly	y state all pertinent dei	tails, and give pert	inent dates, inc	luding estimated	date of starting any proposed		
					•					
	10/23/81	Drilled '	7 7/8" hole	to 3878! p	n 1 T+ E 1	/04 174 -	OC	, 5 1/2" 15.5#		
1	, ,	K=55 Gag	ing and got	- 0 3070 . N	11 1 JC. 5 1	./2" 1/# a	na 96 Jts.	, 5 1/2" 15.5#		
,		1 33 Cas.	ing and set	е @ 3877'. на	Lliburton ce	mented w/	750 sxs.	Lite w/ 15#		
		Saic, 5#	Glisonite,	, and $1/4\#$ Flow	cele. Taile	ed in w/ 2	00 sxs. 5	0/50 POZ Mix		
		$\mathbf{w}/5$ # sal	lt and .5%	CFR-2. Plug o	down @ 2:15	A.M. WOC				
								•		
		•								
			•							
				•						
		·								
						*				
	•			•						
10	I basebar acidiristi is	the lefe==1	ab a second							
10. 1	nereby certify that	// / /	#OOVE IS true and	d complete to the best	of my knowledge as	nd belief.				
	W///	111 br 1								
516 P		Minh to	NI	w.w. = 7\ ~	ea Superint	ondon+		10/27/81		
	Dale R.	crockett	· · · · · · · · · · · · · · · · · · ·	TITLE AL	ea ambariur	endent	DATE			