

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-28193
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Heller Company Trust Com A
8. Well No. 1
9. Pool name or Wildcat Osudo Wolfcamp, West
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3666.8' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER ☐	2. Name of Operator Manzano Oil Corporation 505/623-1996
3. Address of Operator P.O. Box 2107/Roswell, NM 88202-2107	4. Well Location Unit Letter E : 2180 Feet From The North Line and 660 Feet From The West Line Section 24 Township 20 South Range 35 East NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3666.8' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: Plug & Abandon ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/12/93 POOH w/tbg & pkr. Set CIBP @ 11,000' W/35 sks cement on top.
Set 100' cement plug across top of Bone Springs from 7700-7800'.
Set 100' cement plug across 10-3/4" shoe from 4250-4350'.
Set 100' cement plug at Base of Salt from 3600-3700'.
Set 100' cement plug across 16" shoe from 550-650'.
Set 10 sks surface plug.
Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Allison Raney TITLE Engineering Technician DATE April 14, 1993
TYPE OR PRINT NAME Allison Raney TELEPHONE NO. 623-1996

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APR 16 1993

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:
THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE WELL