

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ For ☐

5. State Oil & Gas Lease No.
E-5886

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator <u>Gulf Oil Corp.</u>	8. Form or Lease Name <u>Lea "AG" State</u>
3. Address of Operator <u>P.O. Box 670, Hobbs, NM 88240</u>	9. Well No. <u>2</u>
4. Location of Well UNIT LETTER <u>D</u> <u>880</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>West</u> LINE, SECTION <u>33</u> TOWNSHIP <u>19S</u> RANGE <u>35E</u> NMPM.	10. Field and Pool, or Wildcat <u>in Board. In Indre.</u>
11. Elevation (Show whether DF, RT, GR, etc.) <u>3731' 6K</u>	12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER <u>Completion</u> ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Log. Perf 5843-51' + 5809-17' 4/0" 1/2" JHPF. Spot acid. Acc. w/ 8250 gal 15% NEFE + (24) RCNB's. AIR 5BPM, Avg press 3000 psi, 151P 2050 psi. Inac w/ 48,100 gals x-link, 48,800# sand. 151P 2040, avg press 2100, AR 14BPM. Set cnt ret 5733'. Ig w/ 150 sd gulf mix + 150 sd CL "C" w/TP4 + H₂O. Spot acid 5855'-5655'. Perf 5809-11, 5843-51 w/ (4) 1/2" JHPF. Perf (6) 1/2" JHPF @ 5575'. Set C/BP 5600'. Set cnt ret 5531'. Ig w/ 3000 gal CaCl₂, 3000 gal flow ck, 503 sd CL "H" w/CFR-2. Ig 3400 psi. Dil cnt to 5595'. Ream to 5600'. Tot eq 2000# - OK. Clean out to 5996'. Set cnt ret 5730'. Ig 5809-51' w/ 200 sd CL "H" w/CFR-2.

(Continued)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. D. Prite TITLE AREA ENGINEER DATE 1-9-84

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JAN 12 1984