

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.B.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2086
SANTA FE, NEW MEXICO 87501

Form O-103
Revised 10-1-77

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
A-1212-1

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL FROM O-101 FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Term of Lease Name South Hobbs (GSA) Unit
3. Address of Operator P.O. Box 68, Hobbs, NM 88240	9. Well No. 138
4. Location of well SL/BHL I 2490/2628 South 173/47 UNIT LETTER I FEET FROM THE LINE AND FEET FROM East 4 19-S 38-E TOWNSHIP RANGE NEPM.	10. Field and Pool, or Wildcat Hobbs GSA
15. Elevation (Show whether DF, RT, GR, etc.) 3612.3' GL	11. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING CONS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER cement squeeze ☒	CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to cmt. squeeze water channel from Zone 1 as follows:
MISU and PQH with tbq and sub pump. Plug back from 4273' to 4114' with 20/40 mesh sand (apx 21.2 ft³ sand) Tag top of sand and cap with 5' of calseal (apx 7ft³ calseal) New PBD should be 4109'. RIH with pkr. and tbq, set pkr. at 4000' Establish an injection rate into the perforated intervals 4094-98' and 4102-08', POH. RIH and set cmt retainer at 4025'. Pump 100 sxs of class 'C' neat, reverse out excess cmt., POH, and WOC. RIH and drill out remaining, cmt., calseal, and sand to 4273', POH. Rerun the production equipment and return well to production.

0+5 NMOCD,H 1-JR.Barnett, Hou 1-F.J. Nash, Hou 1-GCC 1-Shell 1-Sun 1-Texaco
1-Petro Lewis

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Harry C. Clark</u>	TITLE <u>Asst. Admin. Suprv.</u>	DATE <u>6-21-84</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR		
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

JUN 26 1984