## State of New Mexico Ener Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

TELEPHONE

DATE

NO.

**DISTRICT I** 

TYPE OR PRINT NAME

(This space for State Use)

APPROVED BY

R.N. GILBERT

OIL CONSERVATION DIVISION P.O. Box 1980, Hobbs, NM 88240 310 Old Santa Fe Trail, Room 206 WELL API NO. Santa Fe, New Mexico 87503 FED STATE X FEE 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.) SOUTH HOBBS UNIT 1. Type of Well: Oil Well X Gas Well Other 2. Name of Operator 8. Well No. ALTURA ENERGY LTD. 3. Address of Operator 9. Pool name or Wildcat 1710 WEST STANOLIND RD, HOBBS, NM 88240 HODDS 505/397-8200 GRAYBURG SAN ANDRES 4. Well Location Unit Letter M 580 Feet From The SOUTH Line and 755 Feet From The WEST Line Section Township Range 38-E **NMPM** LEA County 10. Elevation (Show whether DF, RKB, RT GR, etc.) 3610' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL PLUG AND REMEDIAL WORK ALTERING CASING WORK ABANDON TEMPORARILY ABANDON X **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG & ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. NOTIFY THE NMOCD OF RIG UP. (393-6161) MI. RUPU. POOH W/PRODUCTION EQUIPMENT. RIH W/5.5" CSG SCRAPER TO 4280'. TOP PERF 4300' SET 5.5" CIBP @4250'. TEST CSG TO 500# AND CHART FOR 30 MIN FOR THE NMOCD. NOTIFY THE NMOCD 24 HR BEFORE CSG TEST. CIRC CSG WITH INHIBITED FLUID. SCANALOG TBG OUT OF WELL. RDPU. CLEAN LOCATION. I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE LIFT SPECIALIST

OA TITLE