ORIGINAL SIGNED BY JEERY SEXTON	JAN 1 1 1984
16HED Cathy S. Forman Inc. Assist. Adm. Analyst	1-5-84
 17. Describe Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work/see nucleitos. Moved in completion unit 11-16-83. Removed tree and installed blowout cement at 4177' and drilled out cement, float collar, and cement to 42 with 155 bbl fresh water. Pressure tested casing to 1500 psi for 30 m Ran compensated neutron log and cement bond log from TD to surface. P zones II and III intervals 4170'-86', 97'-4202, 16'-20' and 28'-32' wi packer and 2-7/8" tubing to 4014'. Ran base gamma ray/temp. survey 42 packer to 4244' and pumped 2 bbl 15% LSTNE acid. Pulled up and set th Opened unloader and pumped 23 bbl 15% LSTNE acid. Closed unloader and LSTNE acid. Flushed with 28.6 bbl fresh water. (Tagged acid with rad Ran after treatment survey and indicated channel up. Pulled tubing ant tubing and seating nipple, landing seating nipple at 4250'. Removed b and flanged up well. Ran rods and pump. Moved out service unit 11-23 testing 12-4-83. Tested for 4 days. Last 24 hours pumped 4 B0, 372 Bl Moved in service unit 12-13-83. Pulled rods, pump and tubing. Ran sul 2-7/8" tubing to 3700'. Re-started pump test 12-15-83 and pumped for hours pumped 12 B0, 1002 BW, and 3 MCFD. Completed as an oil well 12-19 producing. 8.1 hereby cently that the information between the complete to the best of my howing and belief. 	preventer. Tagged 90'. Displaced well in. Tested Okay. erforated San Andres th 4 JSPF. Ran 86'-4000'. Lowered e packer at 4014'. pumped 1834 gal 15% ioactive material.) d packer. Ran 2-7/8" lowout preventer -83. Began pump N, and O MCFD. bmersible pump and 5 days. Last 24 20-83 and is currently
NOTICE OF INTENTION TO: SUBSEQUENT PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JQB OTHER OTHER D	ALTERING CASING
15. Elevation (Show whether DF, RT, GR, etc.) 3608.5' GL Check Appropriate Box To Indicate Nature of Notice, Report or Oth	12. County Lea
THE West LINE, SECTION 10 TOWNSHIP RANGE RANGE NMPM.	
4. Location of Well C 1245 North 2475	10. Field and Pool, or Wildcat Hobbs: GSA
AMOCO PRODUCTION COMPANY 3. Address of Operator P. O. Box 68, Hobbs, NM 88240	8. Farm or Lease Name South Hobbs (GSA)Unit 9. Well No. 158
SUNDRY NOTICES AND REPORTS ON WELL'S 1. 01. 01. 01. 01. 01. 01. 01.	7. Unit Agreement Name
U.S.O.B. LAND OFFICE OPERATOR	Sa. Indicate Type of Letse State Free Free 5. State Oti 6 Gas Lease No.
ENERGY AND MINERALS DEPARTMENT DISTRIBUTION BANTA FE FILE DISTRIBUTION COLL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE, NEW MEXICO 87501	Form C-103 Revised 10-1-7
STATE OF NEW MEXICO	

•

APPROVED BY	DISTRICT I SUPERVISOR
CONDITIONS OF	APPROVAL, IF ANYI

TITLE _

DATE

RECEIVED JAN 6 1984 O.C.D. NOBBS OFFICE

Ę,

9