

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name Selby
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>N</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>1</u> TOWNSHIP <u>20-S</u> RANGE <u>35-E</u> NMPM.	10. Field and Pool, or Wildcat Wildcat Delaware
15. Elevation (Show whether DF, RT, GR, etc.) 3654.9' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Swab test apx. 2 days. Ran tubing, packer and seating nipple. MOSU 6-24-84. Ran cast iron bridge plug and set at 5704'. Capped cast iron bridge plug with 35 ft class C cement. POH and LD tubing to 4307'. and spot 25 sx class C cement 4307'-4057'. LD tubing to 499' and spot 25 sx class C cement 499'-249'. Spot 15 sx class C cement surf plug and cut off casing head. Install PXA marker. MOSU 6-26-84.

0+5-NMOCD,H 1-J. R. Barnett, HOU Rm. 21.156 1-F. J. Nash, HOU Rm. 4.206 1-BFC
1-Superior, HOU 1-Superior, Mid

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bonita Cobb TITLE Administrative Analyst DATE 7-23-84
APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE DEC 1 1 1984
CONDITIONS OF APPROVAL, IF ANY: