

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-28979
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT'
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name South Hobbs (GSA) Unit
2. Name of Operator Amoco Production Company	8. Well No. 181
3. Address of Operator P. O. Box 3092 Houston, TX 77253	9. Pool name or Wildcat Hobbs Grayburg San Andres
4. Well Location SL/BHL Unit Letter A/B :1120/1308 Feet From The North Line and 1275/1321 Feet From The East Line Section 5 Township 19-S Range 38-E NMPM Lea County	10. Elevation (Show whether DP, RKB, RT, GR, etc.) 3617.9' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rig up 12-6-89. Acidize perfs 4083'-4206' w/3200 gals 20% HCl using ppi packer @ 4 spacing - 200 gals per setting. Flush to perfs and return well to production 12-9-89.

Before workover: 260 BOPD, 2500 BWPD, 14 MCFD
After workover: 270 BOPD, 2800 BWPD, 17 MCFD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Amelia Hartman TITLE Assistant Admin. Analyst DATE 1-16-90
TYPE OR PRINT NAME Amelia Hartman (713) TELEPHONE NO. 584-7442

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

JAN 23 1990

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: