

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-70

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name
2. Name of Operator AMOCO PRODUCTION COMPANY	8. Farm or Lease Name South Hobbs (GSA) Unit
3. Address of Operator P. O. BOX 68 HOBBS, NEW MEXICO 88240	9. Well No. 183
4. Location of Well SL/BHL F 2540/2609 FEET FROM THE North LINE AND 1423/1342 FEET FROM THE West LINE, SECTION 5 TOWNSHIP 19-S RANGE 38-E NMPM.	10. Field and Pool, or Wildcat Hobbs GSA
15. Elevation (Show whether DF, RT, GR, etc.) 3622.2' GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to reduce water production as follows:

MISU and POH w/ rods, pump, and tubing. RIH w/ cement retainer and set at 4000'. Squeeze with 100SX class C neat and 50SX class C with 4#/5X Tufflog. Reverse excess, POH, & WDC. RIH and drill out to 4125'. Pressure test to 500psi. Drill out to 4200' and circulate clean. Perforate 4146'-50', 4162'-74', and 4178'-83' with 4TSPF. RIH w/ PPI packer spaced to 1' and acidize in one foot intervals 4162'-74' and 4179'-83' with 50 gals of 15% NEFE HCL per setting. Pullup & set packer at 4125'. Pump 1000 gals of 15% NEFE HCL w/ addits. Re-run production equipment and land seating nipple at 4180'. Return well to production.

0+5 NMOC-D-H 1-JRB 1-FJN 1-CMH

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Charles M. Herring</u>	TITLE <u>ADMINISTRATIVE ANALYST (SG)</u>	DATE <u>1/16/86</u>
ORIGINAL SIGNED BY <u>JERRY SEXTON</u> DISTRICT 1 SUPERVISOR	TITLE _____	DATE <u>JAN 20 1986</u>
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JAN 17 1986

O.C.D.
HOBBS OFFICE