

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
A-1212-1

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name South Hobbs (GSA) Unit
3. Address of Operator P.O. Box 68, Hobbs, NM 88240	9. Well No. 188
4. Location of Well UNIT LETTER K 1493/1467 FEET FROM THE South LINE AND 1802/1518 FEET FROM THE West LINE, SECTION 5 TOWNSHIP 19-S RANGE 38-E NMPM.	10. Field and Pool, or Wildcat Hobbs GSA
11. Elevation (Show whether DF, RT, GR, etc.) 3615.5' GR	12. County Dea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒ Perf and Acidize	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to perf and acidize the Grayburg as follows:
POH with production equipment. RIH and set RBP at 4180' and test RBP.
Perforate Grayburg intervals 4004-10', 4012-24', 40-48' and 56-66' w/45SPF
using a 3 1/8 gun. RIH with PPI ppr and set at 3980'. Acidize 4008-10',
12-24', 40-48', and 56-60' in 1' intervals with 50 gals of 15% NE HCL per
ft. (1300 gals total) Retrieve fluid plug + RFC valve. Pull ppr up to 3980'
and acidize Grayburg with 1500 gals of 15% NE HCL gelled acid w/add.
POH with ppr, tlg, and RBP. Run production equipment and return well
to production.

OF 5 NMOC, H 1-JRB 1-FJN 1-GCC 1-PL.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **Eddie W. Seay** TITLE **Asst. Admin. Analyst** DATE **1-30-85**

APPROVED BY **Oil & Gas Inspector** TITLE _____ DATE **FEB - 1 1985**

CONDITIONS OF APPROVAL, IF ANY:

2401 1000

RECEIVED
JAN 31 1985
P.C.S.
HUMAN OFFICE