Pertinent Data

Well:

SHU PW 198

Flac No:

80883601

Field:

SOUTH HOBBS /GRAYBURG-SAN AND/

Brief Date:

09/26/96

Workover Category:

Flex

Radius of Exposure:

0' (500 ppm) & 0' (100 ppm);

Based on 0 mol % H2S

Engineer:

David French

Mail Code:

Home Phone: (713) 957-4892

SOCON:

321-4237

UseriD:

zdlf19 17.130

Secretary:

Cyndy Wright

SOCON:

321-7552

Work Objective:

E - Change Status...PxA,TxA,convert, recomplete, return to prod. from

TXA

Symptoms:

36 - Marginal/Unprofitable well (verylow rate &/or offset oilcut)

Major Code:

O - Other

Minor Codes:

Economics

Estimated Cost: \$ 12,000 (Gross)

General Comments

Production is not economic and well is currently shut-in. Final approval pending partner and NMOCD approval is pending. Salvage value of equipment estimated at \$3,000.

Procedure

Abandonment Procedure

- *** Verify original completion cement job placed sufficient cement behind production casing.
- 1) MIRUSU. (Notify NMOCD 24 hours prior to job)
- 2) RIH w/ Wkstring. Set CIBP at 4055'.
- 3) Cap CIBP w/ 25 sks class "C". Load hole w/ 9.5# brine.
- 4) Spot class C cmt plug 1534-1660'.
- 5) Cap x 10 sks class C cmt at surface.
- 6) Install PXA marker/cut off wellhead.

Engineer: Dave French (713) 366-4237