Submit 3 Copies to Appropriate

State of New Mexico nerals and Natural Resources Department Energy.

Form C-103 Revised 1-1-89

CONDITIONS OF AFFROVAL, IF ANY:

| DISTRICT I P.O. Box 1980, Hobbs, NM 88240 | OIL CONSERVATION DIVISION P.O. Box 2088 | WELL API NO. | |
|---|---|--|--|
| DISTRICT II Santa Fe, New Mexico 87504-2088 2.0. Drawer DD, Ariesia, NM 88210 | | 30-025-29443 | |
| | | 5. Indicate Type of Lease STATE FEE STATE | |
| DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410 | | 6. State Oil & Gas Lease No. | |
| OUNDRY NOT | ICES AND REPORTS ON WELLS | | |
| (DO NOT USE THIS FORM FOR PRODIFFERENT RESE | ICES AND REPORTS ON WELLS IOPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO PROPOSALS, 101) FOR SUCH PROPOSALS,) | 7. Lease Name or Unit Agreement Name | |
| 1. Type of Well: Oll GAS WELL X WELL | OTHER | South Hobbs (GSA) Unit | |
| 2. Name of Operator | | 8. Well No. | |
| Amoco Production C | | 9. Pool pame or Wildcat | |
| 3. Address of Operator Attn: T P O Box 4891, Hous | TY 77210 | Hobbs;Gravburg-San Andres | |
| 4 Well Location SciBHL 11.50 | 58 Feet From The South Line and | 60/940 Feet From The EAST Line | |
| , | 10 30 | NMPM Lea County | |
| Section (0 | Township Range C | c.) | |
| | 1///// 3617.3 GL | <u> </u> | |
| | Appropriate Box to Indicate Nature of Notice NTION TO: | ce, Report, or Other Data SUBSEQUENT REPORT OF: | |
| | | | |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON | | |
| TEMPORARILY ABANDON | CHANGE PLANS COMMENCE DF | | |
| PULL OR ALTER CASING | CASING TEST A | AND CEMENT JOB L | |
| OTHER: | OTHER: | | |
| work) SEE RULE 1103. | ernions (Clearly state all pertinent details, and give pertinent date large (Operations are scheduled to co | | |
| | | | |
| SIGNATURE | | ness Analyst DATE 09/30/96 (713) TELEPHONE NO. 366-7337 | |
| om! | ullo me Sr. Busi | ness Analyst DATE 09/30/96 (713) TELEPHONE NO. 366-7337 | |

Pertinent Data

Well: SHU PW 202 Flac No: 80884001

Field: SOUTH HOBBS / GRAYBURG-SAN AND/

Brief Date: 09/26/96

Workover Category: Flex

Radius of Exposure: 0' (500 ppm) & 0' (100 ppm);

Based on 0 mol % H2S

Engineer: David French

Home Phone: (713) 957-4892 SOCON: 321-4237 UserID: zdlf19 Mail Code: 17.130

Secretary: Cyndy Wright

SOCON: 321-7552

Work Objective:

E - Change Status...PxA,TxA,convert, recomplete, return to prod. from

TXA

Symptoms: 36 - Marginal/Unprofitable well (verylow rate &/or offset oilcut)

Major Code: O - Other

Minor Codes:

Economics

Estimated Cost: \$ 12,000 (Gross)

General Comments

Production is not economic and well is currently shut-in. Final approval pending partner and NMOCD approval is pending. Salvage value of equipment estimated at \$3,000.

Procedure

Abandonment Procedure

- *** Verify original completion cement job placed sufficient cement behind production casing.
- 1) MIRUSU. (Notify NMOCD 24 hours prior to job)
- 2) RIH w/ Wkstring. Set CIBP at 3962'.
- 3) Cap CIBP w/ 25 sks class "C". Load hole w/ 9.5# brine.
- 4) Spot class C cmt plug 1555-1712'.
- 5) Cap x 10 sks class C cmt at surface.
- 6) Install PXA marker/cut off wellhead.

Engineer: Dave French (713) 366-4237