

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division

1625 N. French Dr.

Hobbs, NM 88240

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.
NM 28880

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Rett Federal Com 1Y

9. API Well No.

30-025-29572

10. Field and Pool, or Exploratory Area

Undes Bone Spring

11. County or Parish, State

Lea County, NM

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Nearburg Producing Company

3. Address and Telephone No.

3300 N A St., Bldg 2, Suite 120, Midland, TX 79705

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FSL and 760' FEL, Section 23, T20S, R34E

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1.) Dump 35' cement on existing CIBP @ 10,600' w/ bailer

2.) Set CIBP @ 9,050', dump 35' cement on top

3.) Load hole w/ 9.6# mud

4.) Cut & pull casing @ 7000'

5.) Set 40 sx plug 50' and 50' out of 5-1/2" csg stub. WOC tag

6.) Set 40 sxs plug @ 5560' (Base of 8-5/8" @ 5508')

7.) Set 40 sxs plug @ 3700' (Top of Yates 3660')

8.) Set 40 sxs plug @ 1800'

9.) Set 40 sxs plug @ 1300'

10.) Turn well over to Dan Berry (Landowner) PO Box 160, Eunice, NM 88231 (505) 369-6964

11.) FINAL REPORT.

14. I hereby certify that the foregoing is true and correct

Signed *Kim Stewart*
(This space for Federal or State office use)
(ORIG. SGD) DAVID R. GLASS

Title Regulatory Analyst

Date 08/31/00

Title

PETROLEUM ENGINEER

Date

SEP 01 2000

Approved by
Conditions of approval, if any:

SEE ATTACHED FOR

CONDITIONS OF APPROVAL

Title of U.S. Government work, or work of any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or reports, or to make any material statement which is false.

*See Instruction on Reverse Side

GWW

