ENERGY MO MINERALS DEPA				P. O. BOX 2008						Form C-101 30-025-24735 Levised 10-1-78	
			SANTA FE, NEW MEXICO 87501					SA. Indicate Type of Lease BTATE X FEE			
Ē	1.3.6.3. . AND OFFIC	6	+-1			·		•	.S. Siele Of	I & Gas Louise Nu.	
APPLICATION FOR PERMIT TO DRILL, DEEPEN, OR PLUG BACK											
			-		_				7. Unii Agi	rement Name	
	er of Voll		_	4 3	DEEPEN	amere X				Lease Name	
2. Net		o Inc.				2002 [2]		104 E	N. M. S. Well No.	"F" State	
I. Add	ress el Oper	lar		<u> </u>					10 51-14	3 nd Pool, or Wildcat	
4.100	P. O.				Mexico 88		•			Monument (G-SA)	
•	41.204 41 421	ONIT LETT	enP		ATED	- PECT PROM THE	out				
A#8	330		THE Eas	t u	E OF SEC. 24	TWP. 19-5 act					
							\overline{m}		12. County	XIIIIII	
HH.	iiiiiii			<i>}}}}}</i>			H H		Lea		
\overline{m}											
1111.						19. Froposed Depth	- T	9A. Formation	7777777	20. Rolary or C.T.	
. 1. E .	vetions (340	w wäetker DF	, K T, etc.)	21A. Kind	6 Status Plug. Bond	<u>3965</u>		ravburg-S	an Andre	s Rotary	
	3692'	GR			nket	and braining Congr	CLOC			. Date Work will start	
23.				P	ROPOSED CASING A	ND CEMENT PROGR	A 14		isepten	<u>ber 30, 1986</u>	
	SIZE OF H	IOLE	SIZEOF								
	12-1/		8-	5/8"	24#	SETTING DE	FIN	400		EST. TOP	
<u> </u>	<u>7-7/</u>	8"	5-	1/2"	15.5#	3965'	-	100		<u>Circulate</u>	
•		,				·		1			
					CEMENTING	PROGRAM ·					
	0										
	Surra	<u>ce Casi</u>	<u>.ng</u> : 400 cu	0 sxs (. ft./s	Class "H" ce sx, 15.6 ppg	ment w/2% Ca	aC12	and 1/4	l# Floc	ele (l.18	
			U u	• • • • • • • • •	tage: 400 sx	s 50/50 Poz	Нс			ele (l.18 locele (l.26	
			U u	lst Si	tage: 400 sx cu. ft tage: 600 sx	, s 50/50 Poz ./sx, 14.2]	H c ppg) nt c	ement w/	′1/4#_F ′15#_sa	locele (1.26	
	<u>Produ</u>	<u>ction (</u>	Casing:	lst Si 2nd Si	tage: 400 sx cu. ft tage: 600 sx Flocel 2500')	s 50/50 Poz ./sx, 14.2 j s Lite Weig] e (2.10 cu.	H c ppg) nt c ft.	ement w/ ement w/ /sx, 12.	'1/4# F '15# sa 7 ppg)	locele (1.26	
· · ·	<u>Produ</u>	<u>ction (</u>	Casing:	lst Si 2nd Si	tage: 400 sx cu. ft tage: 600 sx Flocel	s 50/50 Poz ./sx, 14.2 j s Lite Weig] e (2.10 cu.	H c ppg) nt c ft.	ement w/ ement w/ /sx, 12.	'1/4# F '15# sa 7 ppg)	locele (1.26	
•	<u>Produ</u>	<u>ction (</u>	Casing:	lst Si 2nd Si	tage: 400 sx cu. ft tage: 600 sx Flocel 2500')	s 50/50 Poz ./sx, 14.2 j s Lite Weig] e (2.10 cu.	H c ppg) nt c ft.	ement w/ ement w/ /sx, 12.	'1/4# F '15# sa 7 ppg)	locele (1.26	
	<u>Produ</u>	<u>ction (</u>	Casing:	lst Si 2nd Si	tage: 400 sx cu. ft tage: 600 sx Flocel 2500')	s 50/50 Poz ./sx, 14.2 j s Lite Weig] e (2.10 cu.	H c ppg) nt c ft.	ement w/ ement w/ /sx, 12.	'1/4# F '15# sa 7 ppg)	locele (1.26	
	<u>Produ</u>	ther we	lls in t	Ist Si 2nd St this 1/	tage: 400 sx cu. ft tage: 600 sx Flocel 2500') 4,1/4 secti	s 50/50 Poz ./sx, 14.2 p s Lite Weig] e (2.10 cu. Qn are opera	H c ppg) nt c ft.	ement w/ ement w/ /sx, 12.	'1/4# F '15# sa 7 ppg)	locele (1.26	
ABOV VE 2011	Produ All o	ther we	lls in t	Ist Si 2nd St this 1/	tage: 400 sx cu. ft tage: 600 sx Flocel 2500') 4,1/4 secti	s 50/50 Poz ./sx, 14.2 p s Lite Weig] e (2.10 cu. on are opera of the back, sive ba	H copg) ht c ft.	ement w/ ement w/ /sx, 12.	(1/4# F (15# sa 7 ppg) 	locele (l.26 lt and l/4# (DV tool @	
I A BOV VE 2011 Veroby (ened	Produ All o	ther we	asing:	Ist Si 2nd St this 1/	tage: 400 sx cu. ft tage: 600 sx Flocel 2500') 4,1/4 secti	s 50/50 Poz ./sx, 14.2 p s Lite Weig] e (2.10 cu. Qn are opera	H copg) ht c ft.	ement w/ ement w/ /sx, 12.	(1/4# F (15# sa 7 ppg) 	locele (1.26	
LABOV VE 30ml Veroby (gned	Produ All o All o	ther we	asing: asing:	Ist Si 2nd Si this 1/	tage: 400 sx cu. ft tage: 600 sx Flocel 2500') 4,1/4 secti	s 50/50 Poz ./sx, 14.2 p s Lite Weig] e (2.10 cu. on are opera of the back, sive ba	H copg) ht c ft.	ement w/ ement w/ /sx, 12.	(1/4# F (15# sa 7 ppg) (co.	locele (l.26 lt and l/4# (DV tool @ /13/86	
ABOV VE 1041 Heroby gaed C	Produ All o All o C space per c. ever slow	ther we	asing: asing: alls in the posed procession procession for above is procession above is	Ist Si 2nd Si this 1/	tage: 400 sx cu. ft tage: 600 sx Flocel 2500') 4,1/4 secti	s 50/50 Poz ./sx, 14.2 p s Lite Weig] e (2.10 cu. on are opera of the back, sive ba	H copg) ht c ft.	ement w/ ement w/ /sx, 12.	(1/4# F (15# sa 7 ppg) 	locele (l.26 lt and l/4# (DV tool @ /13/86	
I ABOV VE Jon Heroby (gaed PPRQV >HBIV(Produ All o All o C space per c. ever slow	ther we	asing: asing: alls in the posed procession procession for above is procession above is	Ist Si 2nd Si this 1/	tage: 400 sx cu. ft tage: 600 sx Flocel 2500') 4,1/4 secti 4,1/4 secti L. J. Twie Dist.	s 50/50 Poz ./sx, 14.2 p s Lite Weig] e (2.10 cu. on are opera of the back, sive ba	H c ppg) nt c ft. ated	ement w/ ement w/ /sx, 12. by Texa	<pre>/1/4# F /15# sa / ppg) ///////////////////////////////////</pre>	locele (l.26 lt and l/4# (DV tool @ /13/86	