

Monstate #6
Attachment to C-105
(dated 9-24-90)

Perfed Wolfcamp @ 8398-8402', 8406-09', 8413-16', 8426-28', 8436-42',
8436-42', 8457-61' (2 SPF - 56 holes) acidized w/ 5000 gal
15% NEFE. Set cmt ret @ 8390', sqzd perfs w/ 100 sxs.
Perfed Wolfcamp @ 8322-8352, 8358-86' (2 SPF - 120 holes). Set CIBP @
8310' and capped w/ 35' cmt. New PBTD 8275'.
Perfed Abo @ 7974-78', 7987-91', 7993-8018' (2 SPF - 69 holes).
Acidized w/ 5500 gal 15% NEFE. Set cmt ret @ 7964'.
Squeezed perfs w/ 100 sxs cmt.
Perfed Abo @ 7628-30', 33-35', 37-40', 57-59', 75-77', 79-81',
88-90', 7705-11', 18-21', 40-44', 58-63', 70-72', 77-79',
89-91', 7825-27', 38-40', 43', 46-48', 55-58', 82-86',
7915-18', 22-26', 45-50'. (2 SPF - 174 holes) Acidized
w/ 10,000 gal 15% NEFE. Set CIBP @ 7625'. Dumped 10'
cmt on top. New PBTD 7615.
Perfed Abo @ 7238-46', 62-66', 86-88', 93-95', 7306-08', 39-41',
46-49', 55-57', 60-62', 64-66', 70-72', 83-85', 91-94',
7398-7400', 7418-20', 25-28', 42-44', 52-57', 72-75',
82-88', 92-94', 7506-08', 27-30', 44-46', 88-90',
7602-05'. (2 SPF - 172 holes). Set CIBP @ 7250' &
dumped 35' cmt on top. Set CIBP @ 6850' & dumped
10' cmt on top. New PBTD 6840'.
Perfed San Andres @ 5129-62' (2 SPF - 68 holes) Set CIBP @ 5100' &
dumped 35' cmt on top.
Perfed San Andres @ 4200-86', 4350-67' (2 SPF - 210 holes)
Well TA.

SEP 26 1990

OLD
POST OFFICE