



STATE OF NEW MEXICO  
ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT  
OIL CONSERVATION DIVISION  
HOBBS DISTRICT OFFICE

BRUCE KING  
GOVERNOR

February 25, 1993

POST OFFICE BOX 1980  
HOBBS, NEW MEXICO 88241-1980  
(505) 393-6161

Geodyne Operating Co.  
ATT: Barbara Lee  
320 South Boston,

*Samsa Resources Co*

Tulsa, OK 74103-3708

RE: CORRECTING API NUMBERS

Gentlemen:

The Oil Conservation Division has started requiring API numbers for each well on operators C-115 report. As a result of this we have discovered incorrect API numbers on some federal wells. The API number on the federal well(s) listed below does not agree with the API records on file with the Oil Conservation Division office.

LEASE NAME, #, LOCATION	INCORRECT API #	CORRECT API #
Federal 11-20-34, #3-L, 11-20-34	30-025-70013	30-025-30424

We need you as the operator of the well to file a Federal Sundry Notice (Form 3160-5) to the appropriate BLM office stating the correct API # and requesting the API # be corrected in their records. You need to advise them this corrected number was obtained for the Oil Conservation Division. Also asking for the effective date when you may start using the correct number on BLM & MMS forms. If there is any questions, please call the Oil Conservation Division, District I Hobbs, NM (505) 393-6161.

Yours very truly,

OIL CONSERVATION DIVISION

*Jerry Sexton*

Jerry Sexton  
District I, Supervisor

JS:dp  
CC: BLM, Santa Fe, well file

