_	<u></u> . •			_	
1	Submit 3 Copies			Form C-103	
to Appropriate District Office		Energy, Minerals and Natural Resources Department		Revised 1-1-29	
		OIL CONSERVATION DIVISION			
	DISTRICT I P.O. Box 1980, Hobbs, NM \$8240			WELL API NO	
	P.O. Box 2088  VISTRICT II Santa Fe, New Mexico 87504-2			30-025-31136	
	P.O. Drawer DD, Artonia, NM \$8210	Dama I e, I vew IV	1204-700	S. Indicate Type of Lance	
	DISTRICT III			STATE X FEE	
	1000 Rio Brizot Rd., Azzec, NM \$7410			6. State (XI & Gee Leese No.	
ſ	SUNDSY NOT	COSC AND DEPOSTS O		U-3033	
I	SUNDRY NOTICES AND REPORTS ON WELLS  ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)				
1				7. Lease Name or Unit Agreement Name	
l				Coyote State	
	1. Type of Well:	1			
ļ	MEIT MEIT X	OTHER	··-		
	2. Name of Operator Saba Energy of Texas,	Tna		8. Well Na	
-	1. Address of Operator	Inc.	· · · · · · · · · · · · · · · · · · ·	10.7	
l	1603 S.E. 19th St., Su	ite 202 Edmond (	OK 73013	9. Pool name or Wildcat	
ł	4. Well Location	Lee 202 Edmond,	OK 73013	North Pearl	
F 1980 North 1650 Worth					
Ì	Unit Letter:	Feet From the	Line and 10	Feet From The West Line	
ļ	Section 36	Township 195	Range 35E	NMPM Lea County County	
Ż		////// 10. Elevation (Show	whether DF, RKB, RT, GR, etc.)	7/////////////////////////////////////	
Ł		36:	76' GR	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	
	11. Check	Appropriate Box to Ind	icate Nature of Notice, R	eport, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
				ocaociti iici otti ot.	
F	PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
1	EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPHS. DPLUG AND ABANDONMENT XX	
F	PULL OR ALTER CASING		CASING TEST AND CE	L BOL TREME	
c	OTHER:		OTHER:		
_					
	<ol> <li>Describe Proposed or Completed Opera work) SEE RULE 1103.</li> </ol>	tions (Clearly state all pertinent de	ciails, and give pertinent dates, inclu	ding estimated date of starting any proposed	
	5-27-98 Set 5½" CIBP @ 9210;. Capped w/5 sx. TOC @ 9165'. 5-29-98 Spotted 40 sx Class C cement @ 6320'. WOC & tagged TOC @6131'				
Spotted 40 sx Class C cement @ 6320'. WOC & tagged TOC @6131'. Cut & pulled $5\frac{1}{2}$ ' casing from 6268'.					
5-29-98 Spotted 40 sx cement @ 6320'. WOC & tagged TOC @ 6131'.					
5-01-98 Spot 45 sx cement @ 5219'. WOC & tagged TOC @ 5058'.					
	-01-98 Spotted 45 sx cement from 3310' to 3190'.				
	-01-98 Spotted 45 sx cement from 1832' to 1712'.				
-	-01-98 Spotted 45 sx cement from 550' to 430'.				
	-01-98 Spotted 10 sx cement from 20' to surface.				
,4	602-98 Cut off wellhead and installed dry hole marker. Clean location.				
	**All cement was Class C Neat***				
-	Yhanna a da				
	I hereby cartify that the information above is true	I mas complete to the best of my knowle			
	SIGNATURE Fogs Me	<u>-y</u>	muSupervisor	DATE 6/4/98	
	D==== 36			915/	
=	TYPEORPROTENAME Roger Ma	issey 1		твияноне на. <u>570-7087</u>	
	The state of the s				

APR 0 8 1999 %