

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

1. Well No.	30-025- 31212
2. Indicate Type of Lease	STATE ☐ FEE ☒
3. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Lease Name or Unit Agreement Name - South Hobbs (GSA) Unit
2. Name of Operator Amoco Production Company	8. Well No. 228
3. Address of Operator P. O. Box 3092, Houston, TX 77253	9. Pool name or Wildcat Hobbs Grayburg - San Andres
4. Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>North</u> Line and <u>1140</u> Feet From The <u>West</u> Line Section <u>5</u> Township <u>19-S</u> Range <u>38-E</u> NMPM Lea County	
10. Elevation (Show whether <u>DP</u> , <u>RKB</u> , <u>RT</u> , <u>GR</u> , etc.) <u>3624.6</u> GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data.	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: <u>Perforate & Acidize</u> ☒	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MI & rig up service unit & pull tubing & ESP equip.
Run workstring X pkr X establish rate into Zone I perms. Squeeze perms 4014-4048 w/50 sx Class "C" cmt w/4#/sx tuff-plug, followed by 50 sx Class "C" neat. Reverse out excess X WOC.
Tag top of cmt w/bit & drill-out cmt. Circulate out.
RIH w/csg gun & perf following intervals using 4 SPF: 4112-48, 4155-97, 4206-16, 4222-42, 4250-80.
Acidize new perms w/50 gal/ft 15% NE HCL using PPI pkr @ 2' spacing.
Total acid volume 6900 gals.
POH & prep to run ESP & prod. tbg X return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kim A. Colvin TITLE Asst. Admin. Analyst DATE 8/13/91
713/
TYPE OR PRINT NAME Kim. A. Colvin TELEPHONE NO. 596-7686

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: