Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revisied 1-1-89

District Office

OIL CONSERVATION DIVISION P.O. Box 2088

DISTRICT L. COMPANY To Many May 12 OFFICE COMPANY		
<u>DISTRICT I</u> Santa Fe, New Mexico 87504-2088 P.O. Box 1980, Hobbs, NM 88240		
DISTRICT II	API NO Janeiros	d by 000 N
P.O. Drawer Dd, Artesia, NM 88210	API NO. (assigned by OCD on New Wells) 30-025-31345	
<u>DISTRICT III</u>	5. Indicate Type	
1000 Rio Brazos Rd., Aztec, Nm 87410	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	STATE X FEE
	6. State Oil & (
	N/A	Case Edead 110.
SUNDRY NOTICES AND REPORTS ON WELLS		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"		or Unit Agreement Name
		STATE (NCT-C)
(FORM C-101) FOR SUCH PROPOSALS.)		
1. Type of Well: OIL GAS	7	
WELL X OTHER		
2. Name of Operator		
CHEVRON U.S.A. INC.	8. Well No.	1
3. Address of Operator	9. Pool name or	
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS	EUMONT Y	
4. Well Location Unit Letter P : 660 Feet From The EAST Line and		_
Section 75	36E	5 Feet From The SOUTH Line
10. Elevation(Show whether DF, RKB, RT, GR, etc.)	305	NMPM LEA County
3622 GE		
11 Check Appropriate Box to Indecate Nature of Notice, Report, or Other Data	 	
NOTICE OF INTENTION TO: SUBSEQUENT R	EPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	7	ALTER CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.		PLUG AND ABAN.
PULL OR ALTER CASING CASING TEST AND CMT JOB	7	
OTHER: OTHER: COMPLETION		X
12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including		
esticated date of starting any proposed work! SEE RULE 1103.		
MIRU, TIH W/GIT TAG AT 3549' AND DRILL OUT TO 3600'.		
TEST CASING TO 1000 PSI-OK. LOG HOLE: CCL-GR.		
PERF 3344'-3572' W/4" GUNS, 180 DEG. PHSD.		
ACDZ PERFS W/3000 GALS FO 15% NEFE.		
ACDZ PERFS 3572'-3484' W/1500 GALS OF 15% NEFE. SWAB BACK ACID.		
ACDZ PERFS 3460'-3344' W/1500 GALS OF 15% NEFE. SWAB BACK ACID.		
FRAC PERFS W/68,500 GALS OF 50-50 X-L GEL AND 173,500# OF SAND	•	
FLOW BACK WELL TIH DRILL OUT FILL TO 3595'.		
TIH W/PACKER AND TUBING, SET PACKER AT 3307'.		
LOAD AND TEST ANN. TO 500#-OK.		
RDMO, WELL COMPLETED ON 01-05-92.		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNITURE P. R. Mathews TITLE TECH. ASSISTANT	DATE:	01-07-92
TYPE OF DEBINT MAKE		
TYPE OR PRINT NAME P.R. MATTHEWS	TELEPHONE NO.	(915)687-7812
ORIGINAL SIGNED BY JERRY SEXTON		JAN 09'92
APPROVED BY DISTRICT I SUPERVISOR TITLE	DATE	V V QL
CONDITIONS OF APPROVAL, IF ANY:		