

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <b>30-025-31585</b>
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator <b>Amerada Hess Corporation</b>		6. State Oil & Gas Lease No. <b>B-2052-3</b>
3. Address of Operator <b>P. O. Box 840, Seminole, Texas 79360</b>		7. Lease Name or Unit Agreement Name:  <b>North Monument G/SA Unit Blk. 5</b>
4. Well Location  Unit Letter <b>F</b> : <b>2605</b> feet from the <b>North</b> line and <b>2630</b> feet from the <b>West</b> line  Section <b>19</b> Township <b>19S</b> Range <b>37E</b> NMPM <b>Lea</b> County		7. Well No. <b>22</b>
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		8. Pool name or Wildcat <b>Eunice Monument G/SA</b>

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1-7 thru 1-12-2003

MIRU Key Energy Svc. pulling unit & TOH w/rods & pump. Removed wellhead, installed BOP & TOH w/tbg. TIH w/7" CIBP & set at 3902'. Schlumberger TIH w/4" csg. gun & re-perforated 7" csg. in Grayburg Zone w/2 SPF, total 70 holes at following: 3850'-3876' & fr. 3881'-3889'. Acidized csg. perfs. fr. 3850' - 3889' w/2000 gal. 15% HCL acid. Swabbed well. TIH & pushed CIBP to PBD at 3931'. TIH w/2-7/8" tbg. set OE at 3898'. Removed BOP & installed wellhead. TIH w/pump & rods. RDPU, cleaned location & continued producing well.

JAN 2003  
Hobbs  
OCD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roy L. Wheeler, Jr. TITLE Specialist - Field Admin. DATE January 16, 2003

Type or print name Roy L. Wheeler, Jr. Telephone No. 915 758-6778

(This space for State use)

APPROVED BY GARY WINK DATE JAN 22 2003  
Conditions of approval, if any: OC FIELD REPRESENTATIVE II/STAFF MANAGER

ORIGINAL SIGNED BY  
GARY WINK  
OC FIELD REPRESENTATIVE II/STAFF MANAGER