


Outlet Man Fed #1



- 1- Outlet Man Fed #1 4 320 Co
- 2- 4x20 Permian Heater Inertor
- 3- 210 Fiberglass Water Tank w/ Mt
- 4- 2- 300 Steel Welded Stock Tanks

8-28-93

Bill Custer