Forn. 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

Completion or Recompletion Report and Log form.)

 Lease Designation and Serial No. NM-56264

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals

Use "APPLICATION FO	OR PERMIT—" for such proposals	
SUBMIT	T IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well Solit Gas Other		8. Well Name and No. North Lea Federal 7 9. API Well No. 30-025-31737 10. Field and Pool, or Exploratory Area Quail Ridge Delaware 11. County or Parish, State
1980' FNL & 1980' FEL Sec. 10-T20S-R34E		Lea NM
2 CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other Run Casing	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 11" hole @ 4,459' on October 14, 1992. Drillpipe became stuck in the hole and fishing operations insued for 5 days. The fishing operations proved to be unsuccessful and a cement plug was set @ 3,712' with an estimated top @ 3,512'. The 11" hole was then reamed out to 12 1/4" down to 3,231', and 72 jts of 9 5/8" 36# per foot J-55 ST&C csg was run and set @ 3,228'. The csg was cemented w/ 1,675 sx of lite cement followed by 200 sx of Class "H" cement, and cement was circulated to surface. BLM was notified of the job. WOC 8 hrs and NUBOP, test BOP and csg to 1000 psi for 30 minutes, OK. Continue drlg operations.

4. I hereby certify that the foregoing is true and correct Signed	Tide Petroleum Engineer	Date11-1	2-92
(This space for Federal or State office use) Approved by Conditions of approval, if any:	Title	Date \$3 !	ς

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Form 3160-5 (June 1990)

1. Type of Well

Oil Gas Well

Name of Operator

3. Address and Telephone No.

Read & Stevens, Inc.

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

P. O. Box 1518

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

6. If Indian, Allottee or Tribe Name

NM-56264

SUNDRY NOTICES AND REPORTS ON WELLS
orm for proposals to drill or to deepen or reentry to a different reser

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

Roswell, NM 88202

	1		
	7. If Unit or CA, Agreement Designation		
	8. Well Name and No.		
-	North Lea Federal 7		
	9. API Well No.		
	30-025-31737		

	The Medical Committee of the Committee o	11. Co
1980' FNL & 1980' FEL		
Sec. 10-T20S-R34E		

Quail	Ridge De	elaware
11. County	or Parish, State	

10. Field and Pool, or Exploratory Area

 		Lea	NPI
CHECK APPROPRIATE BOX(s) TO INDICATE NAT	TURE OF NOTICE, REPO	ORT, OF	OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTIO	N
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other Recompletion Recompl	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

TD 11" hole @ 4,459' on October 14, 1992. Drillpipe became stuck in the hole and fishing operations insued for 5 days. The fishing operations proved to be unsuccessful and a cement plug was set @ 3,712' with an estimated top @ 3,512'. The 11" hole was then reamed out to 12 1/4" down to 3,231', and 72 jts of 9 5/8" 36# per foot J-55 ST&C csg was run and set @ 3,228'. The csg was cemented w/ 1,675 sx of lite cement followed by 200 sx of Class "H" cement, and cement was circulated to surface. BLM was notified of the job. WOC 8 hrs and NUBOP, test BOP and csg to 1000 psi for 30 minutes, OK. Continue drlg operations.

14. I hereby certify that the foregoing is true and correct Signed	Tide Petroleum Engineer	Date	11-12-92
(This space for Federal or State of fice Aser) Approved by Conditions of approval, if any:	Tide	Date	కుక

^{13.} Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*