Office <u>District I</u>	State of 14	ew Mexico		Form C-103	
	Energy, Minerals an	d Natural Resource	s	Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API		
811 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION		30-025-319	Type of Lease		
District III	2040 South Pacheco		STA:	·	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, 1	NM 87505		IE LJ FEE Z il & Gas Lease No.	
2040 South Pacheco, Santa Fe, NM 87505			1582	ii & Gas Lease No.	
	S AND REPORTS ON V			me or Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSAL	S TO DRILL OR TO DEEPEN	OR PLUG BACK TO A		5	
DIFFERENT RESERVOIR. USE "APPLICAT PROPOSALS.)	ION FOR PERMIT" (FORM C	2-101) FOR SUCH	Foster		
1. Type of Well:					
Oil Well 🛂 Gas Well 🗆	Other				
2. Name of Operator			8. Well No.		
David H. Arrington Oil & Gas, Inc				3	
3. Address of Operator P.O. Box 2071, Midland, Texas 79702				Pool name or Wildcat Monument Abo	
4. Well Location	102		Wonument	Abo	
. Won Location					
Unit Letter P: 660'	feet from the South	nline and 3	30' feet from	n the East line	
					
Section 34		S Range 36I		County Lea	
1	0. Elevation (Show whe	ther DR, RKB, RT, G	R, etc.)		
	3614' GR				
	ropriate Box to Indic				
NOTICE OF INTE				REPORT OF:	
PERFORM REMEDIAL WORK P	LUG AND ABANDON L	」 REMEDIAL V	VORK	\square ALTERING CASING \square	
TEMPORARILY ABANDON C	HANGE PLANS	COMMENCE	DRILLING OPNS.	☐ PLUG AND ☐	
_		_		ABANDONMENT	
	MULTIPLE [OMPLETION	CASING TES			
	OWIFEETION	CEMENT JO	D		
		[/	
OTHER:			stall Plunger	ď	
OTHER: 12. Describe proposed or completed of	operations. (Clearly state	all pertinent details,	stall Plunger	lates, including estimated date	
OTHER: 12. Describe proposed or completed of starting any proposed work). S.	operations. (Clearly state	all pertinent details,	stall Plunger	lates, including estimated date	
OTHER: 12. Describe proposed or completed of starting any proposed work). So or recompilation.	operations. (Clearly state EE RULE 1103. For Mu	all pertinent details, altiple Completions: A	stall Plunger and give pertinent of Attach wellbore dia	lates, including estimated date	
OTHER: 12. Describe proposed or completed of starting any proposed work). So or recompilation. 9-24-01 - RU PLS slick line. PLS of	operations. (Clearly state EE RULE 1103. For Mu cut paraffin and ran 1.9	all pertinent details, altiple Completions: A	stall Plunger and give pertinent of Attach wellbore dia o 7000'.	dates, including estimated date gram of proposed completion	
OTHER: 12. Describe proposed or completed of starting any proposed work). So or recompilation. 9-24-01 - RU PLS slick line. PLS of 9-25-01 - SITP - 310 psi. Set 2 3/8	operations. (Clearly state EE RULE 1103. For Mucut paraffin and ran 1.9 " tubing stop at 5730'.	all pertinent details, altiple Completions: A	stall Plunger and give pertinent of Attach wellbore dia o 7000'.	dates, including estimated date gram of proposed completion	
OTHER: 12. Describe proposed or completed of starting any proposed work). So or recompilation. 9-24-01 - RU PLS slick line. PLS of 9-25-01 - SITP - 310 psi. Set 2 3/8 slick line. Return well to proposed work.	operations. (Clearly state EE RULE 1103. For Mucut paraffin and ran 1.9 " tubing stop at 5730'. roduction.	all pertinent details, altiple Completions: A	stall Plunger and give pertinent of Attach wellbore dia o 7000'.	dates, including estimated date gram of proposed completion	
OTHER: 12. Describe proposed or completed of starting any proposed work). So or recompilation. 9-24-01 - RU PLS slick line. PLS of 9-25-01 - SITP - 310 psi. Set 2 3/8	operations. (Clearly state EE RULE 1103. For Mucut paraffin and ran 1.9 " tubing stop at 5730'. roduction.	all pertinent details, altiple Completions: A	stall Plunger and give pertinent of Attach wellbore dia o 7000'.	dates, including estimated date gram of proposed completion	
OTHER: 12. Describe proposed or completed of starting any proposed work). So or recompilation. 9-24-01 - RU PLS slick line. PLS of 9-25-01 - SITP - 310 psi. Set 2 3/8 slick line. Return well to proposed work.	operations. (Clearly state EE RULE 1103. For Mucut paraffin and ran 1.9 " tubing stop at 5730'. roduction.	all pertinent details, altiple Completions: A	stall Plunger and give pertinent of Attach wellbore dia o 7000'.	dates, including estimated date gram of proposed completion	
OTHER: 12. Describe proposed or completed of starting any proposed work). So or recompilation. 9-24-01 - RU PLS slick line. PLS of 9-25-01 - SITP - 310 psi. Set 2 3/8 slick line. Return well to proposed work.	operations. (Clearly state EE RULE 1103. For Mucut paraffin and ran 1.9 " tubing stop at 5730'. roduction.	all pertinent details, altiple Completions: A	stall Plunger and give pertinent of Attach wellbore dia o 7000'.	dates, including estimated date gram of proposed completion	
OTHER: 12. Describe proposed or completed of starting any proposed work). So or recompilation. 9-24-01 - RU PLS slick line. PLS of 9-25-01 - SITP - 310 psi. Set 2 3/8 slick line. Return well to proposed work.	operations. (Clearly state EE RULE 1103. For Mucut paraffin and ran 1.9 " tubing stop at 5730'. roduction.	all pertinent details, altiple Completions: A	stall Plunger and give pertinent of Attach wellbore dia o 7000'.	dates, including estimated date gram of proposed completion	
OTHER: 12. Describe proposed or completed of starting any proposed work). So or recompilation. 9-24-01 - RU PLS slick line. PLS of 9-25-01 - SITP - 310 psi. Set 2 3/8 slick line. Return well to proposed work.	operations. (Clearly state EE RULE 1103. For Mucut paraffin and ran 1.9 " tubing stop at 5730'. roduction.	all pertinent details, altiple Completions: A	stall Plunger and give pertinent of Attach wellbore dia o 7000'.	dates, including estimated date gram of proposed completion	
OTHER: 12. Describe proposed or completed of starting any proposed work). So or recompilation. 9-24-01 - RU PLS slick line. PLS of 9-25-01 - SITP - 310 psi. Set 2 3/8 slick line. Return well to proposed work.	operations. (Clearly state EE RULE 1103. For Mucut paraffin and ran 1.9 " tubing stop at 5730'. roduction.	all pertinent details, altiple Completions: A	stall Plunger and give pertinent of Attach wellbore dia o 7000'.	dates, including estimated date gram of proposed completion	
OTHER: 12. Describe proposed or completed of starting any proposed work). So or recompilation. 9-24-01 - RU PLS slick line. PLS of 9-25-01 - SITP - 310 psi. Set 2 3/8 slick line. Return well to proposed work.	operations. (Clearly state EE RULE 1103. For Mucut paraffin and ran 1.9 " tubing stop at 5730'. roduction.	all pertinent details, altiple Completions: A	stall Plunger and give pertinent of Attach wellbore dia o 7000'.	lates, including estimated date gram of proposed completion d drop plunger. RD PLS	
OTHER: 12. Describe proposed or completed of starting any proposed work). So or recompilation. 9-24-01 - RU PLS slick line. PLS of 9-25-01 - SITP - 310 psi. Set 2 3/8 slick line. Return well to p. 9-26-01 - Recovered 113 BO, 52 m.	operations. (Clearly state EE RULE 1103. For Mucut paraffin and ran 1.9" tubing stop at 5730'. roduction.	e all pertinent details, a altiple Completions: A 210" tubing broach t Install plunger surf	stall Plunger and give pertinent of Attach wellbore dia to 7000'. Tace equipment an	dates, including estimated date gram of proposed completion	
OTHER: 12. Describe proposed or completed of starting any proposed work). So or recompilation. 9-24-01 - RU PLS slick line. PLS of 9-25-01 - SITP - 310 psi. Set 2 3/8 slick line. Return well to proposed work.	operations. (Clearly state EE RULE 1103. For Mucut paraffin and ran 1.9" tubing stop at 5730'. roduction.	e all pertinent details, a altiple Completions: A 210" tubing broach t Install plunger surf	stall Plunger and give pertinent of Attach wellbore dia to 7000'. Tace equipment an	lates, including estimated date gram of proposed completion d drop plunger. RD PLS	
OTHER: 12. Describe proposed or completed of of starting any proposed work). So or recompilation. 9-24-01 - RU PLS slick line. PLS of 9-25-01 - SITP - 310 psi. Set 2 3/8 slick line. Return well to personal proposed or completed of the starting	operations. (Clearly state EE RULE 1103. For Mucut paraffin and ran 1.9" tubing stop at 5730'. roduction.	to the best of my know	stall Plunger and give pertinent of Attach wellbore dia to 7000'. Tace equipment an	lates, including estimated date gram of proposed completion d drop plunger. RD PLS harmonia harmo	
OTHER: 12. Describe proposed or completed of starting any proposed work). So or recompilation. 9-24-01 - RU PLS slick line. PLS of 9-25-01 - SITP - 310 psi. Set 2 3/8 slick line. Return well to p. 9-26-01 - Recovered 113 BO, 52 m.	operations. (Clearly state EE RULE 1103. For Mucut paraffin and ran 1.9" tubing stop at 5730'. roduction.	e all pertinent details, a altiple Completions: A 210" tubing broach t Install plunger surf	stall Plunger and give pertinent of Attach wellbore dia to 7000'. Tace equipment an	lates, including estimated date gram of proposed completion d drop plunger. RD PLS	
OTHER: 12. Describe proposed or completed of of starting any proposed work). So or recompilation. 9-24-01 - RU PLS slick line. PLS of 9-25-01 - SITP - 310 psi. Set 2 3/8 slick line. Return well to personal properties of the personal pr	operations. (Clearly state EE RULE 1103. For Mucut paraffin and ran 1.9" tubing stop at 5730'. roduction.	to the best of my know	stall Plunger and give pertinent of Attach wellbore dia to 7000'. Tace equipment an wledge and belief.	lates, including estimated date gram of proposed completion d drop plunger. RD PLS hobbs 000 DATE_11/07/01	
OTHER: 12. Describe proposed or completed of starting any proposed work). So or recompilation. 9-24-01 - RU PLS slick line. PLS of 9-25-01 - SITP - 310 psi. Set 2 3/8 slick line. Return well to period of the slick line. Signature of the slick line information about the slick line. Type or print name. Chuck Sledge	operations. (Clearly state EE RULE 1103. For Mucut paraffin and ran 1.9" tubing stop at 5730'. roduction.	to the best of my know	stall Plunger and give pertinent of Attach wellbore dia to 7000'. Tace equipment an wledge and belief.	lates, including estimated date gram of proposed completion d drop plunger. RD PLS Hobbs 000 DATE_11/07/01 one No. (915) 682-6685	
OTHER: 12. Describe proposed or completed of starting any proposed work). So or recompilation. 9-24-01 - RU PLS slick line. PLS of 9-25-01 - SITP - 310 psi. Set 2 3/8 slick line. Return well to proposed slick line. SIGNATURE Type or print name Chuck Sledge (This space for State use) APPPROVED BY	operations. (Clearly state EE RULE 1103. For Mucut paraffin and ran 1.9" tubing stop at 5730'. roduction.	to the best of my know	stall Plunger and give pertinent of Attach wellbore dia to 7000'. Tace equipment an wledge and belief.	lates, including estimated date gram of proposed completion d drop plunger. RD PLS hobbs 000 DATE_11/07/01	
OTHER: 12. Describe proposed or completed of starting any proposed work). So or recompilation. 9-24-01 - RU PLS slick line. PLS of 9-25-01 - SITP - 310 psi. Set 2 3/8 slick line. Return well to proposed slick line. Return well to proposed slick line. Return well to proposed slick line. Signature of the slick line slick line. Type or print name. Chuck Sledge (This space for State use)	operations. (Clearly state EE RULE 1103. For Mucut paraffin and ran 1.9" tubing stop at 5730'. roduction.	to the best of my known	stall Plunger and give pertinent of Attach wellbore dia to 7000'. Tace equipment an wledge and belief.	lates, including estimated date gram of proposed completion d drop plunger. RD PLS Hobbs OCD DATE_11/07/01_ one No. (915) 682-6685	