Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I OIL CONSERVATION DIVISION P.O. Box 1980, Hobbs NM 88240 WELL API NO. P.O. Box 2088 30-025-32465 DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease STATE X FEE . DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) W. H. Laughlin 1. Type of Well: OIL WELL GAS WELL X OTHER 2. Name of Operator 8. Well No. Marathon Oil Company 6 3. Address of Operator 9. Pool name or Wildcat P.O. Box 552, Midland, TX 79702 Eumont/Y, SR, QN 4. Well Location 1980 Unit Letter North 2250 Feet From The West Line and Feet From The Line 20-S Township 37-E Section Range Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL:3544 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. **NOTICE OF INTENTION TO:** SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: Install Production Tubing OTHER: \_

work) SEE RULE 1103	,	(orang same and per	timent details, and give per till	ent dates, meiud	mg commaten m	ate of starting any prop
1/20/95: MIRU PL with nitrogen. L	J. NU BOP. _anded tubi	RIH with 2 ng @ 3317'.	1/16" production ND BOP. NU Tree.	tubing. RDMO PU	C/O sand	from 3469-366