Submit 3 copies to Appropriate		F	State of					Form	C-103
District Office		Ener	finerals and Nat	tural R	esources Department				ed 1-1-89
DISTRICTI		OIL C	CONSERV	ATI	ON DIVISION	WELL API NO			
P.O. Box 1900, Hobbs, NM 8 DISTRICT II	38240	_	P.O. Bo			WELL API NO	30 025 32518	R	
P.O. Box Drawer DD, Artesia,	NM 88210	Sa	anta Fe, New M	Nexic	0 87504-2088	5. Indicate Typ		5	
DISTRICT III	MM 00210						STATI		FEE 🔀
1000 Rio Brazos Rd., Aztec, N	M 87410					6. State Cil / C	Gas Lease No.		
SU	INDRY NOT	ICES AN	D REPORTS OF	N WE					
(DO NOT USE THIS FOR	M FOR PROP RENT RESER	POSALS TO RVOIR, US	D DRILL OR TO D E "APPLICATION SUCH PROPOSA	EEPEI FOR F	OR PLUG BACK TO A	7. Lease Nam L VAN E ITE	e or Unit Agreeme	nt Name	
1. Type of Well: OIL WELL			THER						
2. Name of Operator	TEXACO EXP	LORATION				8. Well Nc.	14		
3 Address of Operator	P.O. BOX 730					9. Pool Name	or Wildcat		
4. Well Location						L	Weir Blinebr	<u>у</u>	
Unit Letter	M_ :	990	_ Feet From The _	SOU	TH Line and 990	_ Feet From T	he WEST	Line	
Section <u>9</u>		Township.			Range <u>37-E</u> NN	IPM	LEA	COUNTY	
11.	Chook An		on (Show whether D						
			Box to Indica	te Na	ture of Notice, Report				
NOTICE OF I					SL	IBSEQUE	NT REPORT	T OF:	
PERFORM REMEDIAL WORK		PLUG AND			REMEDIAL WORK	[]	ALTERING CASI	NG	
		CHANGE PL	ANS		COMMENCE DRILLING OPE	RATION [7]	PLUG AND ABAN		·
TEMPORARILY ABANDON			5 110						
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:					CASING TEST AND CEMEN OTHER:	T JOB [] ug back & recom	nplete to Weir Bline	bry	🛛
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Cor work) SEE RULE 1103. 8/8/95: MIRU. Released pac 8/9/95: Ran TDT-P log from 4 8/14/95: MIRU. Pickle tubing 8/15/95: Perforated interval 5 (Pmax=4000psi, Pav=3000ps	mpleted Opera cker. Install B0 6265'-4265'. 1 g with 500g 15 578'-5690' wit si, AIR=6 BPM	ations (Clear OP. TOH w RD. 5% HCL and th 2 jspf. Ad	rly state all pertiner with packer and tub d 1 bbl 15% NEFE		CASING TEST AND CEMEN OTHER: pli s, and give pertinent dates, et CIBP @6297' and capped proposed perforations. th 3500g 15% NEFE + 105	T JOB	nplete to Weir Bline nated date of start ent (PBTD=6267')	ing any pro	🛛
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Cor work) SEE RULE 1103. 8/8/95: MIRU. Released pac 8/9/95: Ran TDT-P log from 4 8/14/95: MIRU. Pickle tubing 8/15/95: Perforated interval 5	mpleted Opera cker. Install B0 6265'-4265'. 1 g with 500g 15 578'-5690' wit si, AIR=6 BPM	ations (Clear OP. TOH w RD. 5% HCL and th 2 jspf. Ad	rly state all pertiner with packer and tub d 1 bbl 15% NEFE		CASING TEST AND CEMEN OTHER: pli s, and give pertinent dates, et CIBP @6297' and capped proposed perforations. th 3500g 15% NEFE + 105	T JOB	nplete to Weir Bline nated date of start ent (PBTD=6267')	ing any pro	🛛
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Cor work) SEE RULE 1103. 8/8/95: MIRU. Released pac 8/9/95: Ran TDT-P log from 4 8/14/95: MIRU. Pickle tubing 8/15/95: Perforated interval 5 (Pmax=4000psi, Pav=3000ps	cker. Install B0 6265'-4265'. 1 9 with 500g 15 5578'-5690' wit ii, AIR=6 BPM 9 production ar	ations (Clear OP. TOH w RD. 5% HCL and th 2 jspf. Ad 1, ISIP=1750 nd tested.	rly state all pertiner with packer and tub d 1 bbl 15% NEFE cid treated perforat Opsi).		CASING TEST AND CEMEN OTHER: pli s, and give pertinent dates, et CIBP @6297' and capped	T JOB	nplete to Weir Bline nated date of start ent (PBTD=6267')	ing any pro	🛛
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Cor work) SEE RULE 1103. 8/8/95: MIRU. Released pac 8/9/95: Ran TDT-P log from 8/14/95: MIRU. Pickle tubing 8/15/95: Perforated interval 5 (Pmax=4000psi, Pav=3000ps 8/18/95-8/25/95: Returned to	cker. Install B0 6265'-4265'. 1 9 with 500g 15 5578'-5690' wit ii, AIR=6 BPM 9 production ar	ations (Clear OP. TOH w RD. 5% HCL and th 2 jspf. Ad 1, ISIP=1750 nd tested.	rly state all pertiner with packer and tub d 1 bbl 15% NEFE cid treated perforat Opsi).		CASING TEST AND CEMEN OTHER: pli s, and give pertinent dates, et CIBP @6297' and capped proposed perforations. th 3500g 15% NEFE + 105	T JOB	nplete to Weir Bline nated date of start ent (PBTD=6267')	ing any pro	🛛
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Cor work) SEE RULE 1103. 8/8/95: MIRU. Released pac 8/9/95: Ran TDT-P log from 8/14/95: MIRU. Pickle tubing 8/15/95: Perforated interval 5 (Pmax=4000psi, Pav=3000ps 8/18/95-8/25/95: Returned to	cker. Install B0 6265'-4265'. 1 9 with 500g 15 5578'-5690' wit ii, AIR=6 BPM 9 production ar	ations (Clear OP. TOH w RD. 5% HCL and th 2 jspf. Ad 1, ISIP=1750 nd tested.	rly state all pertiner with packer and tub d 1 bbl 15% NEFE cid treated perforat Opsi).		CASING TEST AND CEMEN OTHER: pli s, and give pertinent dates, et CIBP @6297' and capped proposed perforations. th 3500g 15% NEFE + 105	T JOB	nplete to Weir Bline nated date of start ent (PBTD=6267')	ing any pro	🛛
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Cor work) SEE RULE 1103. 8/8/95: MIRU. Released pac 8/9/95: Ran TDT-P log from 8/14/95: MIRU. Pickle tubing 8/15/95: Perforated interval 5 (Pmax=4000psi, Pav=3000ps 8/18/95-8/25/95: Returned to 8/26/95: OPT test: 191 BO,	cker. Install BC 6265'-4265'. I g with 500g 15 578'-5690' wit i, AIR=6 BPM o production an 0 BW, 146 MC	ations (Clear OP. TOH w RD. 5% HCL and th 2 jspf. Ad I, ISIP=175(nd tested. CF (flowing,	rly state all pertiner with packer and tub d 1 bbl 15% NEFE cid treated perforat Opsi). , 24 hours)		CASING TEST AND CEMEN OTHER: pli s, and give pertinent dates, et CIBP @6297' and capped proposed perforations. th 3500g 15% NEFE + 105	T JOB	nplete to Weir Bline nated date of start ent (PBTD=6267')	ing any pro	🛛
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Cor work) SEE RULE 1103. 8/8/95: MIRU. Released pace 8/9/95: Ran TDT-P log from 8/14/95: MIRU. Pickle tubing 8/14/95: Perforated interval 5 (Pmax=4000psi, Pav=3000ps 8/18/95-8/25/95: Returned to 8/26/95: OPT test: 191 BO, 8/26/95: OPT test: 191 BO,	cker. Install B0 6265'-4265'. 1 9 with 500g 15 5578'-5690' wit ii, AIR=6 BPM 9 production ar	ations (Clear OP. TOH w RD. 5% HCL and th 2 jspf. Ad I, ISIP=175(nd tested. CF (flowing,	rly state all pertiner with packer and tub d 1 bbl 15% NEFE cid treated perforat Opsi). , 24 hours)	t detail	CASING TEST AND CEMEN OTHER: pl s, and give pertinent dates, et CIBP @6297' and capped proposed perforations. th 3500g 15% NEFE + 105	T JOB	nplete to Weir Bline nated date of start ent (PBTD=6267')	ing any pro	🛛
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Cor work) SEE RULE 1103. 8/8/95: MIRU. Released pac 8/9/95: Ran TDT-P log from 8/14/95: MIRU. Pickle tubing 8/15/95: Perforated interval 5 (Pmax=4000psi, Pav=3000ps 8/18/95-8/25/95: Returned to 8/26/95: OPT test: 191 BO,	mpleted Opera cker. Install BC 6265'-4265'. I g with 500g 15 578'-5690' wit i, AIR=6 BPM p production ar 0 BW, 146 MC	ations (Clear OP. TOH w RD. 5% HCL and th 2 jspf. Ad I, ISIP=175(nd tested. CF (flowing,	rly state all pertiner vith packer and tub d 1 bbl 15% NEFE cid treated perforat Opsi). , 24 hours)	t detail	CASING TEST AND CEMEN OTHER: pli s, and give pertinent dates, et CIBP @6297' and capped proposed perforations. th 3500g 15% NEFE + 105	T JOB	nplete to Weir Bline nated date of start ent (PBTD=6267')	ing any pro	🔯
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Cor work) SEE RULE 1103. 8/8/95: MIRU. Released pac 8/9/95: Ran TDT-P log from 8/14/95: MIRU. Pickle tubing 8/14/95: Perforated interval 5 (Pmax=4000psi, Pav=3000ps 8/18/95-8/25/95: Returned to 8/26/95: OPT test: 191 BO, 8/26/95: OPT test: 191 BO,	mpleted Opera cker. Install BC 6265'-4265'. I g with 500g 15 578'-5690' with 578'-5690' with production an 0 BW, 146 MC	the best of my low	rly state all pertiner vith packer and tub d 1 bbl 15% NEFE cid treated perforat Opsi). , 24 hours) 	t detail	CASING TEST AND CEMEN OTHER: pl s, and give pertinent dates, i et CIBP @6297' and capped proposed perforations. th 3500g 15% NEFE + 105	T JOB	nplete to Weir Bline nated date of start ent (PBTD=6267')	bry ing any pro	🔯
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Cor work) SEE RULE 1103. 8/8/95: MIRU. Released pac 8/9/95: Ran TDT-P log from 8/14/95: MIRU. Pickle tubing 8/14/95: Perforated interval 5 (Pmax=4000psi, Pav=3000ps 8/18/95-8/25/95: Returned to 8/26/95: OPT test: 191 BO, 8/26/95: OPT test: 191 BO,	mpleted Opera cker. Install BC 6265-4265'. I g with 500g 15 578'-5690' with production ar 0 BW, 146 MC 0 BW, 146 MC	the best of my local	rly state all pertiner vith packer and tub d 1 bbl 15% NEFE cid treated perforat Opsi). , 24 hours) 	t detail	CASING TEST AND CEMEN OTHER: pl s, and give pertinent dates, i et CIBP @6297' and capped proposed perforations. th 3500g 15% NEFE + 105	T JOB	nplete to Weir Bline nated date of start ent (PBTD=6267')	bry ing any pro	🖾

 $\mathcal{J}_{\mathcal{C}}$

. _. . dø

- 1 - m