Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR

N.M. OIL CONS. COMM	2210
BO BOYORM VASIONED CO	88240
HC 3 Purger Service No. 100 -0135	

....CCION

Expires: March 31, 1993 **BUREAU OF LAND MANAGEMENT** 5. Lease Designation and Serial No. IC 064194 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE 1. Type of Well 8. Well Name and No. Oil Well X Gas Well Unocal "8" Federal #1 2. Name of Operator 9. API Well No. Union Oil Company of California 30-025-32821 3. Address and Telephone No. 10. Field and Pool, or Exploratory Area (915) 685-7607 P. O. Box 671 - Midland, TX 79702 Quail Ridge Morrow (Gas) 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 75^{0} 660' FWL & 1980' FNL of Sec. 8, T-20-S, R-34-E Lea County, N. Mexico CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12. TYPE OF ACTION TYPE OF SUBMISSION Change of Plans Abandonment Notice of Intent New Construction Recompletion Non-Routine Fracturing Plugging Back X Subsequent Report Water Shut-Off Casing Repair Conversion to Injection Altering Casing Final Abandonment Notice X Other R&C intermediate csq Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 5-25-95-Start drlg. new formation 07:00 AM. 6-10-95-Finish drlg 12 1/4" hole @ 10:45 AM---circ & cond hole---ran 2 stage fld caliper @ 5220' & 3188'. R&L 120 jts + 1 pc (5199') 8 5/8" 32# BCK-55 LSS 8rd ST&C new ERW csg set @ 5220'--amtd 1st stg w/400 sx Howco Lt Prem Plus w/1/4# sx Flocele, 12.4 ppg, 2.20 y f/b 200 sx Howco Prem Plus w/2% CaCl, 14.8 ppg, 1.43 y-did not bump plug-bleed press off--checked float, held 0.K.-2-dropped bomb--opened DV tool w/950 psi--circ DV tool f/4 hrs--did not circ any cmt off DV tool--now cmt'g 2nd 6-11-95-Omtd 2nd stage w/1500 sxs Howco Prem Plus w/10% salt, 1/4# Flocele, 12.4 ppg, 2.20 yld f/b 200 sxs Howco Prem Plus--did not circ cmt--ran temp survey--TOC @ 900'. 6-12-95-Test csg to 1500 psi, test O.K. Drlg new formation @ 4:30 PM. Hard & Illa 14. I hereby certify that the foregoing is true; and correct 6-27-95 Drilling Clerk (This space for Federal or State office use)

Approved by ________ Conditions of approval, if any: